

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 29 T 52N R 35W S 29 T 52N R 35W S _____ T _____ R _____	PCC D9-D10 PCC D10-D9
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/27/2011 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(PCC D9-D10 North of Ravine) A point on the N-S 1/4 line of Section 29 on the northerly bank of a  
ravine. Not established in the original survey.

(PCC D10-D9 South of Ravine) A point on the N-S 1/4 line of Section 29 on the southerly bank of a  
ravine. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(PCC D9-D10 North of Ravine) Established the point on the northerly rim of a deep ravine on a  
straight line between the North and South 1/4 corners of Section 29 1376.84' south of the North 1/4  
corner, 3446.15' north of the South 1/4 corner, and 636.21' north of a similar monument set this date  
on the 1/4 line at the southerly rim of the ravine.

(PCC D10-D9 South of Ravine) Established the point on the southerly rim of a deep ravine on a  
straight line between the North and South 1/4 corners of Section 29 2809.94' north of the South 1/4  
corner, 2013.05' south of the North 1/4 corner and 636.21' south of a similar monument set this date  
on the 1/4 line at the northerly rim of the ravine.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(North) Set 1"IDx32" I.pipe w/4" alum. MDNR cap  
Set measuring nail with MDNR tag in the side of:  
9" Y.Birch N15E 10.85' mrkd "POL BT"  
6" Y.Birch N63E 8.05' do  
4" Y.Birch S42E 8.10' do  
4" Y.Birch N61W 16.9' do  
Set sq'd Cedar post adjacent.  
Bearings are magnetic.

(South) Set 1"IDx32" I.pipe w/4" alum. MDNR cap  
Set measuring nail with MDNR tag in the side of:  
10" Hemlock N44W 5.65' mrkd "POL BT"  
6" Y.Birch N68E 16.55' do  
4" Sugar S15W 16.95' do  
6" Maple S63W 6.7' do  
Set sq'd Cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 08/01/2011

For the Michigan Department of Natural Resources, Forest Management Division

