

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 18 T 52N R 36W	2 (GCDB 160500)
	S 18 T 52N R 36W	7 (GCDB 200460)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 11/04/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(2-Sec. 18) East 1/16 corner between Sections 7 and 18. Not previously monumented.

(7-Sec. 18) North 1/16 corner between Sections 17 and 18. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(2-Sec. 18) Established the position for the corner midway and on the Section line between Section
corner 1327.79' east and Quarter corner 1327.79' west.

(7-Sec. 18) Established the position for the corner midway and on the Section line between Section
corner 1465.80' north and Quarter corner 1465.80' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" Ironwood N81°E 14.7' mrkd "1/16S BT"
5" Ironwood S21°W 15.75' do
5" Ironwood S79°W 8.55' do
4" twin Ironwood N26°E 5.2' do
Set sq'd cedar post adjacent.
E= 7853992.758 N= 238093.533

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
18" Y.Birch N43°E 14.75' mrkd "1/16S BT"
4" B.Ash S17°E 7.9' do
4" B.Ash S65°W 27.0' do
5" Sugar N02°W 13.8' do
Set sq'd cedar post adjacent.
E= 7854383.488 N= 237638.066

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0502: N= 234995.272 m. E= 7857774.766 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

