FEB 1 8 1994

COMMISSION

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

For corners in Ionia		Filing Requirement of Act 74, Mich. P.A. 1970		70	93 K (
		1 . (.)	00.1.//	₽ ()	ST RECO P3
_TC	(County)	Located In:	Corner Code ##	Joins M. I	DEC DEC
	_	- ENT - OUT	T 10	E E	
1.	Public Land Survey	т <u>5N</u> <u>R</u> 8 <u>W</u> Т R	<u>I-13</u>	g (Fundamental Programme 127
		T R		QQQ _{AN}	P REC
		T R		EEOS	HIGAN NIT RECORD RECORD
2.	Property Controlling	S T R		5	G 8 1
	in Section	S T R			
3.	Miscellaneous	S	F	Register of Deeds Stamp	& File Number
	Property in Sec.	S T R			
1	Lot No. B	Recorded Plat			
5.	Private Claims			A B C D E F	G H I J K L M
-				2 5 4-	
				3	
	Manager 1 April 2	:		4 - 7 - 8 - 9 -	10-11-12-
l,	Marinus Mulder	, in a field survey onSepuirements of P.A. 74, Michigan P.A. 0	STEMPER 16 , 1993 , 1970 the corner points mentioned	5	
		conformance with regulations and		6 18 17 16	15-14-13-
	•	actions of the United States Departm		7	
	-	a Court of Law and/or that the corner th the rules of the Michigan Board of		8 19 20 21 21 21 2	22-23-24-
		e-established, monumented, re-m	onumented, recovered, found as	10 30 29 28	
•	ressed below:	armera all in the same tawa and	d roman mou ha ranavdad	11 29 28	27 26 25
NO	on this certificate.	orners, all in the same town and	range, may be recorded	12 31 32 33	34 35 36
				13	
· А.	Description of original r	monument and accessories and	for subsequent restoration:		·
This	corner was first	t set by U.S. Deputy St	rveyor, John Mullet in	1831. A wood pos	t was set .
wite	iessed by: 11" Mar	ole N 84° E / links, an	nd a 13" Maple N 45° W 3	2/ links. ic corner bevever	- Thomas
Ther	re is no writtenic	County Surveyor perform	or's perpetuation of the med a survey in the NE	1/4 of Section 35	June 24 & 25
of 1	872 In the note	es he states that he fo	ound the center of sect	ion set by former	County Surveyor
A.C.	Smith. This lea	eds me to believe that	the corners to Section	35 were located	and perpetuated
A.C. Smith. This leads me to believe that the corners to Section 35 were located and perpetuated Professional Surveyor, Brian Reynolds #31602 recorded I-13 in March of 1988 which is recorded in					
Liber 2 page 288. Reynolds notes he found an iron.					
			pplied in restoring or reestablishir		
The iron which Reynolds recorded seemed to be too far West in relationship with the South 1/4					
corner of Section 35 and too far East with the South 1/4 corner of Section 34. The distance was					
about 11 feet in question. A search with a backhoe was made about 11 feet East of the 5/8" pipe and a stone pile was found in the gravel road about 18" deep. There were some large stones and					
smaller stones around the larger ones. I accepted this as the correct position of I-13. A 3/4"					
x 36" steel rod was set near the center of the stone pile. OVER					
					•
C	Description of manumer	at for corner and accessories as	tablished to perpetuate locating t	he position of the corner	
	•			·	
		rod with a 2 3/4" diam	neter cap stamped "Ionia	a County, P.S. 258	oz. with the
	owing witnesses:	_			Section 18 1
		school house N 58° W 7			
		power pole S 7° W 68.8			
Nail & tag Northeast side 5" Ash S 50° E 93.92' Northeast corner old school house N 39° W 89.08'					
				•	
		1	.•		
Oi~-	ad by	ad a middle	Date Oc	ctober 21, 1993	
•	ed by		Date		
Surv	eyor's Michigan License	No. <u>25863</u>		ROYED BY MICHIGAN STATE BOARD OF LAI	NO SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975
			THE 1107 TAGE 54		REVISED MAY 14, 1975 REVISED JAN., 1983

William Co Est

