

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FEB 15 2001

SECTION

For corners in IOSCO Located In: _____ Corner Code # _____

1. Public Land Survey T 24N R 9E D-E-5 #9
T _____ R _____ Reference Corner
T _____ R _____
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____
in Section S _____
T _____ R _____
T _____ R _____
3. Miscellaneous S _____
Property in Sec. _____
4. Lot No. _____, Recorded Plat _____

066 2000

STATE OF MICHIGAN
IOSCO COUNTY
FILED
15 DEC 2000 2:24:42 PM
BONITA M. COYLE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

5. Private Claims _____

I, WILLIAM E. WOODS P.S., in a field survey on OCT. 16, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: ORIGINAL GOVERNMENT NOTES

SET POST 22.00 CHAINS WEST OF G-7
Y. PINE 18" N49°E 62 LKS
Y. PINE 18" N12°E 63 LKS

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 10-11-2000

James H. Kranger

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1967: JOHN C. MILLER

LOUD ISLAND VIEW SUBDIVISION SHOWS SECTION LINE
ON DESCRIPTION TAIL AND CROSSING LOT 1

1971: RICHARD L. MILLER

CHIPPEWA HEIGHTS SHOWS SECTION LINE RUNNING EAST FROM B-

2000: WILLIAM E. WOODS

MEASURED WEST ON SECTION LINE EXTENDED FROM E-5
INTERSECTED LAKE AT 1360 FEET G.L.O. MEASURED 1452 FEET
WEST OF E-5, 92 FEET OUT IN THE LAKE, SET REFERENCE CORNER
1357.53 WEST OF E-5

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

5/8" REROD & REMON CAP REFERENCE CORNER 1357.53 WEST OF E-5

W. PINE 20" N20°W 40.61' NAIL & TAG
OAK 20" N20°E 50.45' NAIL & TAG
TWIN OAK 20" & 14" N75°E 54.26' NAIL & TAG
S.W. COR. STEEL SEAWALL S15°E 20.48'
E. EDGE S65°W 2.87' STEEL SEAWALL

Signed by William E Woods

WILLIAM E. WOODS P.S.

Surveyor's Michigan License No. 25882

Date 12-06-2000

