LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	corners	in

(County)	_ Located In:	Corner Code #			Ŷ	
 Public Land Survey Property Controlling in Section 	T R T R T R T R T R T R T R T R T R T R	4	×	~		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Doc	odo Stoma 9 Fills N.		
4. Lot No. , Red 5. Private Claims	corded Plat		A B C D E	E F G H I J		
instructions of the United States [a Court of Law and /or that the c	74, Michigan P.A. of 1970, the corner pegulations and rules therefore as require Department of the Interior, Bureau of La orner points mentioned in lines 3, 4 and	ed in the current manual of survey and Management or by a decree of 5 above were in conformance with	6 -18 -17	9101; 16151;	13-	
re-established, monumented, recover	of Land Surveyors or by a Decree ered, found as expressed below:	of a Court of Law; established,	8 19 20	_21222	324	
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range,		10 30 29 11 12 31 32	-28 - 27 - 20 - 33 - 34 - 3!	525	
A. Description of original monument and accessories and/or subsequent restoration:						

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1"IDx28" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:

3" Aspen S81°E 10.9'

mrkd "X X"

Northwest 1/16 corner, Section 8. Not previously monumented.

2" Spruce N34°W 28.7'

do

2" Tamarack N27°W 14.45'

do

4" Cherry S06°E 6.7' "1/16S BT" 1" capped iron pipe on 1/16 line East 200.01'

Set sq'd cedar post adjacent. E= 7906018.070 N= 151708.876

OF MICHIO STEPHAN J. SZYSZKOSKI LAND SURVEYOR AND SUR

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum). Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Surveyor's Michigan License No.

Date

06/03/2014

33986

Revised Oct., 1995