

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 24 T 46N R 34W	1-4
	S T R	(GCDB 620371)
	S 13 T 46N R 34W	4-5
3. Miscellaneous Property in Sec.	S T R	(GCDB 624460)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 01/27/16 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-4, Sec. 24) A Point on the West 1/16 line of Section 24 between 1/16 corners #1 and #4. Not previously monumented.

(4-5, Sec. 13) A Point on the North 1/16 line of Section 13 between 1/16 corners #4 and #5. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-4, Sec. 24) Established the position for the corner on the West 1/16 line of Section 24 642.00' south of 1/16 corner #1 Section 24, and 678.67' north of the unmonumented position for 1/16 corner #4 (intersection of 1/16 lines).

(4-5, Sec. 13) Established the position for the corner on the North 1/16 line of Section 13 311.00' east of 1/16 corner #4 and 1007.06' west of the unmonumented position for 1/16 corner #5 (midway between L5 and L6).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1-4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap stamped POL W-W Sec 24.
Set measuring nail with MDNR tag in the side of:
8" Cedar N45°E 11.0' mrkd "POL BT"
17" Cedar S85°E 23.2' do
6" twin Cedar S85°W 23.25' do
12" Cedar N67°W 26.0' do
Set sq'd cedar post adjacent.
E= 7884066.396 N= 178025.835

(4-5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap stamped POL N-N Sec 13.
Set measuring nail with MDNR tag in the side of:
4" Cherry N25°W 12.9' mrkd "POL BT"
21" Cedar N54°E 24.2' do
12" Tamarack S02°W 17.25' do
15" Tamarack S59°W 18.95' do
Set sq'd cedar post adjacent.
E= 7884190.970 N= 179424.803

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.409 m. E= 7879234.515 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/17/2016

For the Michigan Department of Natural Resources, Forest Resources Division