REMONUMENTATION

FEB 1 6 1999

Filed under Remonumentation Act 345 of 1990 TIBER 1 PAGE 298

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

| HUE E | | v | |
|-------|----|----------|--|
| STATE | OF | MICHIGAN | |
| LEN | WE | E COUNTY | |
| | FI | LED | |

| For | corners in | | | 10 DEC 1998 9:46:41 AM |
|---|--|--|--|---|
| | (County) | Located In: | Corner Code # | VICTORIA J. DANIELS REGISTER OF DEEDS |
| 2. i 3. | Public Land Survey Property Controlling In Section Miscellaneous Property in Sec | TR TR TR TR S 18 | 2 | Register of Deeds Stamp & File Number |
| 4. l 5. f | ot No, R | ecorded Plat | | A B C D E F G H I J K L M |
| do h in lir curre Mana abov Cour | nes 1 and 2 above were ent manual of survey instr agement or by a decree of e were in conformance w | equirements of P.A. 74, Michigan P in conformance with regulations a ructions of the United States Depart a Court of Law and/or that the corrith the rules of the Michigan Board | A. of 1970, the corner points mentioned and rules therefore as required in the riment of the Interior, Bureau of Landiner points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a e-monumented, recovered, found as | 2 3 4 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 9 10 30 29 28 27 26 25 |
| NOT | TE: Not more than 4 on this certificat | | n and range, may be recorded | 11 12 31 32 33 34 35 36 |
| A. | Description of origina | al monument and accessories | and/or subsequent restoration: | |
| | The original pat The Peer Group 1882 James Bla 1907 In J.L. Ric 1964 Walter Fr East. 1973 Werner S 1976 Kenneth S of Section 18 1992 I did a sui iron on line betw | believes this is intended to air found stake and stones a chard's records "found drove azier did a survey 1320' sou commer set a Hex head bolt Suydam survey shows distance in the south part of the eveen the E 1/4 cor and the S | mery Crofoot was for the Middle of be the NW Cor. of the Middle Sind shows distance West to 1/4 control in the pavement by re-tracing Mince West of 1796.60 feet to iron West Subdivision of Section 18 | something he found in the fence line to the |
| B. | Description of corner | evidence found and/or method | l applied in restoring or reestablishin | ng corner: |
| | September 21, ² asphalt. | 1998 Found bolt and replac | ed it with 5/8" X 3' re-rod and set | a monument box in base course of new |
| C. | Description of monun | nent for corner and accessorie | s established to perpetuate locating | the position of the corner: |
| | 5/8" X 3' re-rod v not established I the best available NE corner of co Iron pipe East Survey mark s | with Lenwee County Remon by original government surv le evidence of the position of oncrete block porch S 60° | cap stamped P.S. 13040. This eyors. This monument is accept the comer. W 107.16 . Hickory West 65.43 | position |
| | | | 0,1 ,1 1 | TOWAL STATE |

Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Skune Rukard Date 11-3-98

Signed by_

Surveyor's Michigan License No. _13040

Date *Nov. 10, 1998*