## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirement of Act 74, Mich. P.A. 19	970
LIVINGSTON Located in:	Corner Code#	1996 NOV 14 P 1: 20
	NR_3E	NANCY HAVILAHD REGISTER OF DEEDS LIVINGSTON COUNTY, MI. 48843
2. Property Controlling S T T in Section S T T S. Miscellaneous S T Property in Sec. S T	R	L.S.C.#569m  Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
5. Private Claims		1
requirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules therefore as re- United States Department of the Interior, Bureau of Lar that the corner points mentioned in lines 3, 4 and 5 ab	on 10-24, 19 96 do hereby state that under comer points mentioned in lines 1 and 2 above were in quired in the current manual of survey instructions of the nd Management or by a decree of a Court of Law and /or love were in conformance with the rules of the Michigan urt of Law; established, re-established, monumented,	3 4 7 8 9 10 11 12 5 6 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same on this certificate.	town and range, may be recorded	9 10 30 29 28 27 26 25
·	,	11 32 33 34 35 36
A. Description of original monument and access GLO: 1825 White Oak 35", South White Oak 32", North	sories and/or subsequent restoration: 76 degrees West, 10 links 72-1/2 degrees East, 37 links	CONWAY
Found 1/2" iron rod, when exc	r method applied in restoring or reestablishing correavated to set remonumentation pithis iron at 2.0 ft. below grade	ine found
*Additional descriptions and	historical information on back o	of this sheet.
C. Description of monument for corner and acce	essories established to perpetuate locating the pos	sition of the corner:
"Livingston Co. Monumen	/TAG N/S 8" TREE. /TAG S/S 28" MAPLE.	a. brass cap, stamped
Signed by 10024	Date	etober 24, 1996
Surveyor's Michigan License No. 19834		E PROMPE LINE

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN. 1983
REVISED JAN. 1983

## CONWAY TOWNSHIP, T4N, R3E

D-11, THE SOUTH 1/4 CORNER OF SECTION 29 AND THE NORTH 1/4 CORNER OF SECTION 32.

FIELD: 6-24-1996 DARRELL D. HUGHES AND ASSOCIATES, FOWLERVILLE.

Found a 1/2" iron rod, 0.2' below grade and 1.5' North of centerline asphalt pavement. Also, found a PK nail 0.5' South of centerline and 2.25' SE from iron rod. In 1972, Oscar Boss finds 3/8" iron and shows 3 witness points. In 1991 Hughes finds PK nail with witness' checking to 1972 ties, does not mention 3/8" or 1/2" iron. Measures from PK, East to E-11 agree with Boss' 1979 measurement and West to C-11 also agree with same. Measures North to D-10 vary. The 1/2" iron rod agrees with irons found for Boss survey North and East of corner.

I recommend the acceptance of the 1/2" iron for the position of D-11. OK for GPS.

- 1825 Sylvester Sibley, Deputy U.S. Surveyor, "West corrected between 29 and 32, 39.85 chains set 1/4 post", P.7-7A
- 1872 Miles Bullock divides Section 29. P.8-8A
- 1973 Oscar Boss sets center of Section at intersection of 1/4 lines. No witness' to D-11, P,9-9A.
- 1974 March, Oscar Boss re-divides above survey, shows witness'. P.10-10A
- 1974 Oct. Boss files Act 74. P.11
- 1979 Gary Boss divides Southeast 1/4 of Sec. 29. No witness' for D-11. P.12-12B
- 1979 Boss survey shows corner with witness' P.13
- 1991 Hughes surveys in Southeast 1/4 of Section 29, two witness' agree from 1973. P.14-14C
- 1996 Witness comparison list. P.15