## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.44 NR ... 74

	MackinacCOUNTY
DESCRIPTION OF CORNER	1/4 Cor. between Secs: 9-10
DESCRIPTION OF CORNER MON	NUMENT 1" Pipe with 4" Brass Cap
WITNESSES TO CORNER	12" W. Pine (1/4s NBT) 515°E 131 Lks.
	14" Tamarack (dead) (1/4s NBT) N24°E 62 Lks.
<del>-</del>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 cor. from two Tam. B.Ts. N14°W 12 Lks., standing good condition and S18°W 22 Lks., tree down. Cor. found by D. Bonner, Ass't D.F. Cor. placed and wit. 5/21/59 with J. Halbach, D.F. and B. McDonald, Aide.

RIBUTYORS STAIL

SIGNED Billy D. Buckler DATE 7/29/59