

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Macomb Located In: Ray Twp Corner Code #
(County)

1. Public Land Survey T 4N R 13E F-13
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

SURVEY &
RECORD DOCUMENTATION

APR 20 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert D. Kohn, in a field survey on November 30, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1817	Post	W. Preston	N/A	G.L.O. Notes
1978	P.K. Nail	W. Coulter	#14760	LCRC L2932 P831
1979	P.K. Nail	G. Avendt	#16034	Survey L3069 P232
1980	Found P.K. Nail	K. Thompson	#16054	Survey L3148 P894
1988	Replaced P.K. Nail	H. Avey	#15396	LCRC L4353 P443



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No corner was found occupying this position. Witness ties from L.C.R.C. L4353 P443 were used to reset a P.K. Nail in this position. All 4 witness ties are common from above mentioned L.C.R.C. and L.C.R.C. L2932 P831.

Field measurements were observed between the following corners:

E-13 to F-13	F-13 to G-13	F-1 to F-13
2699.25' meas.	2670.25' meas.	106.59' meas.
2640.00' rec. G.L.O.	2640.00' rec. G.L.O.	106.66' rec. L2932 P831
2699.09' rec. L4353 P443	2669.56' rec. L3069 P232	106.59' rec. L4353 P443
	L3148 P894	

ACCEPTED BY THE MACOMB COUNTY SURVEY PEE GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 7-27-96
William E. Scderberg
WILLIAM E. SCDERBERG, P.S., CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the existing P.K. nail with a 1.17" diameter brass marker stamped "Mac Co Act 345" drilled directly into concrete bridge deck with asphalt paving.

Due West 106.59' Mac Co remon. cap & iron #26459 in mon. box (F-1) Macomb Twp.
N51°E. 15.72' N.E. corner post @ N.E. corner of bridge
S48°E. 15.80' S.E. corner post @ S.E. corner of bridge
S.62°W. 29.65' S.W. corner post @ S.W. corner of bridge

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by Robert D. Kohn
Surveyor's Michigan License No. #26459

Date November 30, 1996