REMONULLINA DE

- OCT 3 1 1994

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Require	ment of Act 74, MICH. P.A.	1970
Manistee	Located in:	Corner Code ##	REGISTER'S OFFICE MANISTEE COUNTY
1. Public Land Survey	T 23N R 16W	<u> </u>	#94-449 AT 10:50 A.M. SEP 2:9 1994
	T R T R T R		Penny Q. Penera) REGISTER OF DEEDS
	S T R		•
3. Miscellaneous	S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Rec			A B C D E F G H I J K L M
5. Private Claims	/		2 6 5 4 3 2 1 1 3
Bruce J. Jenema	Augu	st 15 94	4 7 8 9 10 11 12 12 15
do hereby certify that under requirin lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a Cabove were in conformance with the Court of Law; established, re-expressed below:	rements of P.A. 74, Michigan P.A. o onformance with regulations and ions of the United States Departi ourt of Law and/or that the corner the rules of the Michigan Board of	d rules therefore as required in the ment of the Interior, Bureau of Lar rpoints mentioned in lines 3, 4 and I Land Surveyors or by a Decree o	ne ne 7   15   15   15   15   15   15   15
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11 12 31 32 33 34 35 36 13
A. Description of original monument and accessories and/or subsequent restoration:			
One-quarter corner of I-8 1839 James Highl Beech 10" S83°W 27 1908 E.W. Manchester Witness: Beech 8" Survey by NW Survey	bee GLO Surveyor 1/4 links Hemlock "Found Cooks witnes N5°W 12 links	n post between section 12" N50°W 17 lin ss possibly" Beech 10" S25°W	ns 22 & 23 ks 24 links Book A
B. Description of corner evid	dence found and/or method a	pplied in restoring or reestable	lishing corner:
I-8 Found 4"x4" squarecorded Liber 3 of 1	are concrete monument Plats, pages 26-30,	t from the Plat of Po 1917.	ortage Park Addition,
•			
I-8 W 1/4 corner of Manistee County Mark careful and faithful 16" Oak N75°E 9.50	Section 23, T23N, R er (2 1/2"x30" steel re-establishment of	16W, Replaced concret pipe with brass cap) the position of the	and accepted as a original corner and witness by
5" W. Pine S64°W 12" Maple N13°W 18 12" Oak S27°E 22.5	<ul> <li>according to the coun as amended, (being the</li> </ul>	ratified by the Manistee ty plan adopted pursuant to for State Survey and Remonumer Review:  APPROVED	P.A. 345 of 1990, At ACV MCL 54.261 Marine Marine
Bull.	Luneren	Date	4-8-94
Signed bySurveyor's Michigan License,	25850		ORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197
· · · · · · · · · · · · · · · · · · ·		r	REVISED MAY 14 1975