

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

2/18/95 JLP

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

240

For corners in

MIDLAND (County)	Located In:	Corner Code #
1. Public Land Survey	T15N R1W	C-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

14 AUG 95 3:04 P.M.

BEVERLY J THAYER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, PAUL B. LAPHAM, in a field survey on MAY, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-9 Corner common to Sections 20, 19, 30 and 29

1852 AUSTIN BURT, POST, W. PINE 8" S14°E 6 LKS., W. PINE 10" N22°W 19 LKS.

NO C.S.R.

5-5-78 JEROME SCHAFER, FOUND 1/2" ROD 1" DEEP

6-25-90 PAUL LAPHAM, FOUND 1/2" IRON SURVEY & L.C.R.C.

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was
presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Corner common to Sections 20, 19, 30 and 29

Found 1/2"x18" Iron per Surveys by Schafer and Lapham.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

SURVEY &
REMONUMENTATION

JUL 1995

RECORDING

Corner, C-9 was approved for remonumentation at a Peer Review Committee Meeting on 7-18, 19 95.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Corner common to Sections 20, 19, 30 and 29

Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box.
Accepted as best available evidence of the accepted position of the corner.

S40°E 52.16' - N&T IN POWER POLE
N45°E 79.2' - N&T IN 15" OAK
N60°E 88.16' - N&T IN 18" OAK
N60°W 126.50' - N&T IN 8" PINE (NEW)

Signed by Paul B. Lapham
Surveyor's Michigan License No. 9433

Date 7-21-95

