## Land Corner Recordation Certificate **Attachment B to 2016 Annual Grant Agreement**

Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2016 State Survey and Remonumentation **Grant Agreement** 

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County Edenville Township Corner **Corner Type Survey Township** Code Original Public Land E1 16N R 1W Survey Corner • MCL 54.202(g) MCL 54.262(g) R 4 5 5 **Property Controlling** Corner S 6 - 1<del>8</del> -16 15 -- 14 -- 13 6 • MCL 54.202(i) S R 7 R MCL 54.262(h) S 19 20 21 22 23 24 -8 S 9 10 30 25 29 28 27 26 10 Protracted Public Land Survey R Corner 11 MCL 54.202(k) \_ 12 32 33 34 - 36 12 \_13<sub>A</sub> MCL 54.262(i)

# Part A: Corner(s) History

E-1 - 1832 - GLO - H. Parke - Intersect N. Bdy 50 L. West of Post

Set Post on N. Boundary

- 1) Pine 24" N83°W 10 L.
- 2) Pine 20" S59°E 26 L.
- 1852 GLO Dependent Resurvey A. Burt N0°30'E 83.26 Intersect N. boundary 34 L. East of old corner. Old line marked
- 3) Paperage 15" S61°E 27 L.4) Maple 16" S64°W 45 L.
- 1917 CSR P. 393 F. J. Gibbs Sec. 5 Survey Set Pine Root post at average dist. on true line
  - 5) Pine Stp. S80°W 27
  - 6) Pine Stp. N16°W 33

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
T16N R1W Code <u>E1</u>
Page 2 of 2

#### Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

<u>E-1</u> – Closing corner common to Section 4 & 5, T16N, R1W – No GLO evidence found. From remains of Gibb's witnesses found a 2 ½" x 1' long pine root stake point in low area. Local resident Derek Staley witnessed this recovery. Dug for evidence of the standard corner 33' East but nothing was found there. A 5/8" rebar of unknown origin was found N61°37'W 9.75' from stake. Accepted Gibbs stake as the best available evidence of the position of the original corner.

### Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

E-1 - Replaced Pine root stake point with stamped 4" DNR Aluminum Cap on 1" x 4' long galvanized iron pipe. Place stake alongside monument as memorial. Set Blue Composite Post 1' South.
 S10°E 11.60' to set Nail & Tag in W. side 4" R. Maple N61°37'W (grid) 9.75' to Fd. 5/8" rebar
 N16°W 22.35' to set ½" x 24" long smooth iron rod in centerline 24" ± White Pine Stump (#6)

S84°W 18.49' to set ½" x 18" long rebar in centerline 18"± White Pine Stump (#5)

East 33.00 to 'E13'; T17N, R1W - DNR Monument

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
11/11/2015	N43°48'51.3560"	W84°26'48.7064"	2011	2010

Position from Static GNSS observations from 2 local OPUS Base stations adjusted by Least Squares.

i, staig vi. Movean, in a field survey on 140v. 11, 2010, certify under the requirements of	the State Survey and
Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation A	ct, 1970 PA 74, MCL
54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuate	d or monumented as
described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.	

McVEAN ROFESSIONA

URVEY No.

39088

OPESSION

Craig W. McVean

Professional Surveyor's License No.: 39088

Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601

I, Brian D Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on 08/03/2016 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson Date

Professional Surveyor's License No.: 26454