TETT - WELL

### MONTCALM COUNTY REMONUMENTATION PROGRAM

# SECTION

### LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

For corners in													
Montcalm (County)	-	Located In:		Corner Code #			1	STATE OF MICHIGAN					
	!	Reynolds Township						MONTCALM COUNTY RECORDED					
Public Land Survey	Sec	T 12N R 7 T R	10W	K-09	<del> </del>	-		27 0	CT 1999 LORI A				
2. Property Controlling	S	TR_				-		R	EGISTER	OF DE	EDS		
in Section 3. Miscellaneous Property in Sec.	\$ \$ \$	T R T R					Register	r of De	eeds St	amp 8	k File N	lumbe	r 
4. Lot No, Re	ecorded P		· · · · · · ·										
5. Private Claims							۱A	. В (	C D E	F (	; H I	J K	L M
							2	6	5	4	3	2	1
do hereby certify that under in lines 1 and 2 above were	requireme	nts of P.A. 74,	Michigan P.,	A. of 1970, t	he corner po	ints mentioned	3 4	·7 ·	8	9	10	11	12
current manual of survey ins Management or by a decree above were in conformance	structions of a Court	of the United S of Law and/or	tates Depar that the con	tment of the	e Interior, Br entioned in I	ureau of Land ines 3, 4 and 5	6	18	-17	16	15	- 14	13
Court of Law; established expressed below:							8	19	20	21	22	23	24
NOTE: Not more than 2 on this certificat		, all in the sar	me town a	nd range,	may be re	corded	9 10 11 -	30	29	28	27	26	25
A. Description of origina 1837, October 19 <sup>th</sup> , Abne	al monume	ent and acces	sories and	/or subseq	uent restor	ation:	- 1	31	32	33	34	35	-36
North between sections Beech 8"	25 and 2 N36°E	6, 80.00 Chai 13 links	ns set com	er to section	ons 23,24,2	25,26.	13 -						***************************************
Beech 10" 1899, September 1 <sup>st</sup> and Pine Stump 36"	2 <sup>nd</sup> , Heni	V 17 links ry M. Caukins °W 66 ½ linł	, County S	urveyor, At	NE corner	of section too	k NBT.						
1912, June, E.D. Youdan, 23,24,25,26, Found H.A. Set transit at hole and r	(Page 37 J. Caulkin	, Notes from 0 NBT Pine 8	County Sur Stump 35"	S62 ½°W 6	36 ½ links (	36.9 feet) had	been r	emove	ed.	<del>)</del> )			
took NBT White Oak 3"		S68 ¾°E		71 feet									
White Oak 4"		S53 ¾°W	-	139 fee	t								
Corner Fence Po 1977, June 6 <sup>th</sup> , Gerald J.		S53 ¾°E 7741, Survey #	#77082, S∈	41 feet et iron NE C	Corner Sec	tion 26 Reynol	lds Tow	nship					
Liber 502 Page 1217, Pine 8"	S70°E					·			TUE N	NETTO A I	14 OOL	uma ou	
Pine 12"	N40°E	61.9 feet					GROUP	AS TH	ie offic	DIAL CO	DRNER	UNDER	RVEY PEEL
Twin Oak	N15°V	V 97.4 feet		(Continue	d on Back.	)	PUBLIC	ACT 34	5 OF 199	O AT A O	MEETING	HELD	6/18
B. Description of corner										William	رے کے Tingley	DS Ch	nirmon
Found ½ rebar with broker found Railroad Rail, Loc						top surface of	paveme	ent		## HIRCH	i ingrey	, F3, GH	allillatt
USGS Monumen	t	N45°E	,	39.7 feet									
Found nail SW si Found nail SW si				67.5 feet 75.5 feet									
Found nail SE side		the second second	_	S55°W	66.4 feet								
C. Description of monur Set Remonumentation Mo						ite locating the	e positic	on of th	ne corne	er:	toringa, .	277	
USGS Monumen	t	N45°E		39.7 feet					A STANLEY	Children's	SRESKED!	18 1 / Ja	
Found nail SW si				67.5 feet					* *	LIIW 'S	JAM G.		4
Found nail SW si Found nail SE sid				75.5 feet S55°W	66.4 feet				Exil		GLEY SSION	AL X	
Set nail and tag \$				N30°W	55.3 feet				THE STATE OF THE S	Sum	/EYOR	2.5	Terri.
This corner is accepted as a careful and faithful perpetuation of the position of the original corner.													
Signed by 100	- <b>6</b> 14 -	0.7	) 		Date	8/18	1	999		Pag.	C. Carrette		
Surveyor's Michigan Licen	ise No	30104	7		pare	y I o	PPROVED BY		N STATE DA	MRD OF L	AND SI IPA	YORS IN	28 197
Carrey or o miorilyan Eloch						PURM A	י ירעטעבט פן	, MICHIGA	SINIE DC	AND OF L	TANCE OF THE	REVISED	. 20, 1977 AAY 14, 1975 D JAN., 1983

PAGE 138

#### Continued (K-9, 12-10)

1982, June, Glen Hackbardt, #25844, Found Railroad Rail set by County Surveyor in 1910, 15" down near road intersections, set ½" rebar over Railroad Rail, Liber 2 Page 10.

MSGS MonumentN45°E 39.7 feet Pine 10" S60°E 67.32 feet Pine 12" S30°E 75.50 feet

S55°W 66.40 feet Pole 1985, April 30th, Glen Hackbardt, #25844, Survey #78833, SW Corner Section 24 1/2" Rebar over RR Iron,

Liber 585 page 136

MSGS Mon. N45°E 39.7 feet Pine 10" S60°E 67.32 feet Pine 12" S30°E 75.50 feet Pole S55°W 66.40 feet

1986, October 27th, Glen Hackbardt, #25844, Survey #79209, Found 1/2" Rebar, Liber 601 page 260

**USGS Concrete Monument** 

N45°E

Pine 10" Pine 12" S60°E

67.32 feet

39.70 feet

66.40 feet

S30°E

75.50 feet

**Utility Pole** 

S55°W

1990, March 23<sup>rd</sup>, William Tingley. #30104, Survey #90070, found Rebar at NE Corner Section 26 with the following distances:



1993, September 20<sup>th</sup>, Kevin Roosien, #31604, Survey #931195, SW Corner Section 24, T12N, R10W, "Rerod" verified previous recording, Liber 713, 0051.

1995, April 4, William Tingley, #30104, Found 1/2" rebar over R.R. Rail.

MSGS Mon.

N45°E 39.7 feet

Pine 10"

S60°E

Pine 12"

S30°E

67.32 feet 75.50 feet

Pole

\$55°W 66.40 feet

SURVEY & REMONUMENTATION

DEG - 3 1999

SECTION