For corners in

LIBEP 1951 PAGE 679

10:101

STATE OF HIGHIGAN COUNTY OF PERKERCH

10% Offic 23 PM 3:50

7	
1500	
Carrie	والمنافية المعارفة والمعارفة والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة والمنافرة
	OF PETES

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970


Mı	uskegon COMMUNE	Located In:	Corner Code ##	
1.	Public Land Survey	T 11N R 17W	A 8	
		T R	<u> </u>	
		T R		
		T R		
2.	Property Controlling	S T R	• *	
	in Section	S	•	!
3.	Miscellaneous	S T R		
	Property in Sec.	S T R		

Register of Deeds Stamp & File Number

Lot No. _ ___ , Recorded Plat ___ Private Claims _

I, Ralph W VanRiper in a field survey on November 29 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1/4 Corner common to Section 19, T 11 N, R 17 W and Section 24, T 11 N, R 18 W, Fruitland Township. Post set by GLO Surveyors in 1837 (Beech 10", S 80° W, 28 L) Maple 8", N 73° W, 21 L)

MCRC, 1950's Witness Sheets: 3 Witnesses
MCRC, Current Witness Book: 5/8" Rod, with 7 Witnesses Recorded Survey by Donald Sandel, LS No. 25870 in L. 1646, P. 164

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Steel Rod in Asphalt pavement of Duck Lake Road Verified corner location with existing witnesses.


> POSITION OF SAID RECORDED CORNER REVIEWED & RATHFIED BY MUSICEGOM COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

> > June 4, 1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 2 3/4" Cast Iron Monument with County Survey Cap

N 37° E 75.29' Found Spike in W side of 18" Cherry Found Spike in S side of 22" Maple Set Spike in E side of 16" Oak Set Spike in E side of 14" Pine Set Spike in W side of 10" Maple N 55° E 48.45 43.76' South S 25° W 52.02' s 35° W 56.35 N 50° W 48.45 Found Spike in E side of 18" Maple



Surveyor's Michigan License No. __

Date /

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

1 500