LIBEP 1951 PAGE 694

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEPTION (FOR CORD

MAR 2 1 1997

	COMMISS	ION Eiling Boguis	em necondation centre	A 1970 (IFC 23 PM 3: 51
Foi	r corners in	riing nequii	ement of Act 74, Mich. P.	
	Muskegon	Located In:	Corner Code ##	COLAR COESTAR
1.	Public Land Survey	т <u>11N в 17W</u> т <u> </u>	F_13	
	Property Controlling in Section Miscellaneous	T R T R S T R S T R S T R		Register of Deeds Stamp & File Number
	Property in Sec.			
		corded Plat		A B C D E F G H I J K L M
do l in l' cur Mai	hereby certify that under requi ines 1 and 2 above were in c rent manual of survey instruct nagement or by a decree of a C	rements of P.A. 74, Michigan P.A. onformance with regulations ar tions of the United States Depar tourt of Law and/or that the corne	c. 9 , 19 96 of 1970, the corner points mention of rules therefore as required in timent of the Interior, Bureau of Ler points mentioned in lines 3, 4 a of Land Surveyors or by a Decree	and 7
	ort of Law; established, re- pressed below:	established, monumented, re-	nonumented, recovered, found	as 9 10 30 29 28 27 26 25
ИО	TE: Not more than 4 corr on this certificate.	ners, all in the same town a	nd range, may be recorded	11 32 31 32 33 34 35 36
Α.	Description of original mo	nument and accessories and	d/or subsequent restoration:	13
·	South 1/4 Corne Post set by GLO N 21° E, 25 L)	r of Section 33, Surveyors in 183	T 11 N, R 17 W, 37 (Pine 12", N 3	Fruitland Township 6° W, 45 L) ( Pine 12'',
			Rod with 3 Witne con with 4 Witnes	
3.	Description of corner evid	dence found and/or method	applied in restoring or reesta	blishing corner:
	Found 5/8" Pipe	in Monument Box	in Asphalt pavem	ent of River Road
	Verified location	on with existing	Witnesses.	May 7, 1996
				POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUCKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990
٥.	Description of monument	for corner and accessories	established to perpetuate log	ating the position of the corner:
				Cap in Monument Box
	N 12° E 38.44' N 22° E 51.16' N 55° E 56.00' S 50° E 50.33' S 20° W 48.36' S 40° W 46.81'	Set Spike in W Set Spike in W Found Spike in Set Spike in E	E side of 12" Pinside of 8" Oak side of 8" Pine S side of 12" Pinside of 10" Pine side of 10" Pine	RALPH W.

Surveyor's Michigan License No. 16946

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983