

SURVEY & REMONUMENTATION

#951

DEC 07 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 290 PAGE 28

For corners in
Missaukee
(County)

Located In:

Corner Code #/

MISSAUKEE COUNTY MICHIGAN

RECORDED OCT 28 1994 115
p 16

Carolyn Flare
REGISTER

Register of Deeds Stamp & File Number

- | | | |
|------------------------------------|--------------------------|------------|
| 1. Public Land Survey | T <u>21N</u> R <u>8W</u> | <u>1-9</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, J. Dean Geers, in a field survey on October 7, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- I-9) 1853 GLO post by John Brink, Deputy Surveyor
Sugar 30 N 49 1/4 W 7, Sugar 24 N 62 1/2 E 28
- I-9) 1972 M. McClung LCRC Liber 1, Page 110: Found Iron, no witnesses given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- I-9) Section Corner common to Sections 22, 23, 26 and 27

Found 1" pipe in monument box per Liber 1, Page 110 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in centerline of East-West road, in centerline of road to South, and $\pm 5'$ East of centerline of road to the North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- I-9) Set 1/2" Iron and Missaukee Co. monument in monument box

S 44 W - 50.79 - Set Iron on East side Tele Riser
S 48 E - 52.45 - Set Iron
N 30 W - 54.65 - Set Iron @ Southeast corner Tele Riser
N 34 E - 54.72 - Set Iron

Signed by *J. Dean Geers* Date 8/8/94

Surveyor's Michigan License No. 33977

Peer Group Reviewed and Approved

Date: 10-26-94

J. Dean Geers, Missaukee Co. Representative

