

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Missaukee
(County)

Located In:

Corner Code #

1. Public Land Survey

T23NR 7W

M-7

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, J. Dean Geers, in a field survey on June, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- M-7) 1838 GLO Section Post by John Brink, Deputy Surveyor; Hemlock 9-S14W-35, Hemlock 12-N52W-14
M-7) 1991 Case LCRC, Liber 1, Page 827; Set 1/2" Rerod on Township line on line at proportional distance between Found West 1/4 Corner, Section 18 and Found Northwest Corner Section 30. N12W -Twin 8" White Pine-16.70, S06W -5" Oak-11.18, S53E-6" Oak-32.35, S64W-10" White Birch-25.08
M-7) 1997 DNR LCRC, Liber 1, Page 1135; Found and accepted 1/2" Rerod as recorded in Liber 1, Page 827; Twin White Pine-N12W-16.70, 5" Oak-S06W-11.18, 6" Oak-S53W-32.35, 10" White Birch-S64W-25.08

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

- M-7) Section Corner common to Section 13 and 24, T23N, R7W and Section 18 and 19, T23N, R6W. Found 1/2" Rerod as recorded in Liber 1, Page 827 and 1135. This corner is accepted as a careful and faithful re-establishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-7) Replaced Found 1/2" Rerod with 5/8" x 36" Rerod and Missaukee County Monument
S50E 32.37 8" Maple
S10W 11.15 6" Maple
S65W 25.06 14" Twin birch
N10W 16.70 16" Twin Balsam


Peer Group Reviewed and Approved

Date: 10-29-97

J. Dean Geers, Missaukee Co. Representative

Signed by

Surveyor's Michigan License No. 28977



SURVEY &
REMONUMENTATION

JAN 16 1998

SECTION

Date 11-6-97