

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0447

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>MONTMORENCY</u> (County)	Located in: BRILEY TWP.	Corner Code # G-3
1. Public Land Survey	T <u>30</u> R <u>2E</u>	<u>G-3</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:07:31

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, DONALD E. MARLATT, in a field survey on MAY, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6	5										
3												
4	7	8										
5												
6	18	17										
7												
8	19	20										
9												
10	30	29										
11												
12	31	32										
13												

A. Description of original monument and accessories and/or subsequent restoration:

G-3 CORNER COMMON TO SECTIONS 3-4-9 & 10.
G.L.Q. COR. SET BY LEWIS CLASON IN APR. 1840. FIR 6" N34°E 25 L., CEDAR 14" S76°W 14 L.
FRANK SMITH P.S. #754 NOTES: FOUND CEMENT POST, STUMP OF GOV'T B HERE FEB. 1950
MADE NBT CEDAR 6" S10°E 11.0', CEDAR 3" N25°W 12'.
COUNTY ROAD COMMISSION NOTES: NO DATE. MONUMENT N45°E 50' MONUMENT, S45°W 50' MONUMENT.
D.E. MARLATT P.S. #18660 ACT 132 DATED 8/15/92 FOUND CONC. MONUMENT. S64°E 10.86' 8" CEDAR,
S20°E 7.87' 14" CEDAR, S50°W 50' CONC. MONUMENT, N50°E 50' CONC. MONUMENT (TYP. F.S.).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-3 CORNER COMMON TO SECTIONS 3-4-9 & 10.
FOUND CONC. MONUMENT
S60°E 10" CEDAR 8.7'
S15°E 16" CEDAR 7.95' R.
N10°E 20" SPRUCE 14.64'
S50°W CONC. MONUMENT 50' R.
N50°E CONC. MONUMENT 50' R.

APPROVED BY
PEER GROUP

JUL 18 00

L.D.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3 CORNER COMMON TO SECTIONS 3-4-9 & 10.
PLACED REMON CAP ON EXISTING MONUMENT.
S60°E 10" CEDAR 8.70'
S15°E 16" CEDAR 7.95'
N10°E 20" SPRUCE 14.64'
S50°W 50' CONC. MONUMENT
N50°E 50' CONC. MONUMENT

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660.
APPROVED BY PEER GROUP ON JULY 18, 2000 AS A PERPETUATION OF THE ORIGINAL GOV'T CORNER.

Signed by Donald E. Marlatt
Surveyor's Michigan License No. 18660

Date 12/4/2000

