

MAY 16 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 00012 Page 0205

COMMISSION

For corners in

MONTMORENCY (County)	Located In:	Corner Code ##
HILLMAN TWP.	T 31N R 4E	D - 13
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-01-1996 09:41:46

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, DONALD E MARLATT, in a field survey on 7 - 1, 19 96,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

D - 13 SOUTH 1/4 CORNER SEC. 32
CORNER SET BY LEWIS CLASON 3-18-1839
TAM 7"-N39W-35, TAM 5"-N10E- 11
ACT 74 BY KEN OSTLING L. 1, P.328, 8-17-82. SET DNR MONUMENT. BY S.P. METHOD.
8"BALSAM S15°W 3.4', 12"TAMRACK S26°E 34.5'.
DNR SURVEY 8-1982. SURVEY REPORT IN FILE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D - 13 SOUTH 1/4 CORNER SEC. 32
FOUND DNR MONUMENT.
8"BALSAM S15°W 3.4', 12"TAMRACK S26°E 34.5'

**APPROVED BY
PEER GROUP**

JUL 12 96

L.B.B.

NORTH CORNER COMMON TO SEC'S 4 & 5 IS 77"WEST


NO EVIDENCE OF ORIGINAL CORNER

NOTE: MSHD SURVEY DATED 4-5-1966 WAS NOT ACCEPTED FOR CORNER POSITION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D - 13 SOUTH 1/4 CORNER OF SEC. 32, T31N, R4E.
LEFT DNR MONUMENT IN PLACE (1"PIPE WITH 4"CAP)
S24°E 16"SPRUCE 34.67'
S15°W 12"BALSAM 3.26'
N64°W 8"POPLAR 13.55'
N18°W 8"POPLAR 33.7'

WITNESSES MARKED WITH 30 PENNY SPIKES & P.S. TAGS#18660.
APPROVED BY PEER GROUP JULY 12, 1996 AS THE BEST AVAILABLE EVIDENCE
OF THE POSITION OF THE ORIGINAL CORNER.



Signed by Donald E Marlatt

Date 10/28/96

Surveyor's Michigan License No. 18660