LIBER 18604 PC 257

LAND CORNER RECORDATION CERTIFICATE	
Filing Requirement of Act 74, Mich. P.A. 1970	
For comers in	
Oakland Corner Code #	
(Coulcing) West Bloomfield Township	\$ 9.00 MISCELLANEOUS RECORDING
1. Public Land Survey T2N R9E E-4	\$ 2.00 REMONUMENTATION
T R	18 JUN 98 8:17 A.N. RECELPTH 40A
TR	PAID RECORDED - OAKLAND COUNT
<u>TR</u>	LYNN D. ALLEN, CLERK/REGISTER OF REET
2. Property Controlling S T R	
3. Miscellaneous S T R	301
2. Property Controlling STR	Compliance with ACT 345, P.A. 1990
1322 21 2000	ADDROVED ON: 4/21/98 JS
The state of the s	OAKLAND COUNTY REMONUMENTATION
4. Lot No, Recorded Plat 5. Private ClaimsSECTION	PEER GROUP COMMITTEE
	Register of Deeds Stamp & File Numl
1. Huston K. Kennedy , in a field survey on March 12 , 1998 o hereby state the requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 an	RALLINIES STATES
conformance with regulations and rules therefore as required in the current manual of survey insti-	uctions of the 2 - 9 - 1 - 5 - 1 - 3 - 1 - 2 - 1 - 1 -
United States Department of the Interior, Bureau of Land Management or by a decree of a Court that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of	the Michigan "IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,	monumented, 4 - 1 - 8 - 9 - 10 - 11 - 12
recovered, found as expressed below:	5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	6 10 17 16 15 14 13
on this certificate.	7 + + + + + + + + + + + + + + + + + + +
	8 -19 - 20 - 21 - 22 - 23 - 24
	9 4 4 4 4 4 4 4 4 4 4 4
	10 30 29 28 27 26 25
A. Description of original monument and accessories and/or subsequent restore	ation:
1817-GLO Carpenter, D.S.; Set Post 10" White Oak S14 1/2" E 55 Links; 18"	
Black Oak N 8 1/2°W 44 Links 1.) 1983-Hubbell, PS #12022; LCRC L.8340, Pg.884 - Fnd Concrete 13	
Monument with 3/8" Iron Rod	
2) 1979-Nowak PS #13300: Survey L.7558, Pg.99 – Object found not stated, no witnesses	
3.) 1979-Nowak, PS #13300; Survey L.7558, Pg.100 - Object found not stated, no witnesses	
4.) 1979-Nowak, PS #13300; Survey L.7558, Pg.101 – Object found not stated, no witnesses5.) 1979-Nowak, PS #13300; Survey L.7558, Pg.102 – Object found not stated, no witnesses	
6 \ 1979-Nowak PS #13300; Survey L.7558, Pg.103 Object found	not stated, no witnesses
7.) 1979-Nowak, PS #13300; Survey L.7558, Pg.104 - Object found not stated, no witnesses (con't on back of LCRC)	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
1908-Kennedy Surveying, Inc. — Kennedy, PS #17623 — Fnd a 4" diameter Concrete Monument with 3/8" fron Rod 0.30 fee	
below the surface and is 90 ± feet South of the centerline of North S	nore Drive extending to the Northwest & East, which ha
a biturninous surface.	
Witnesses from LCRC #1, Survey #10 & witnesses from Oakland County Road Commission were used to recover and ve	
the location of the found 4" diarneter Concrete Monument with 3/8" In	on Rod.
I accepted the found 4" diameter Concrete Monument with 3/8" Iron Rod as the best evidence of the original corner positon	
FIELD MEASURMENTS BETWEEN	
	E-4 to E-5
<u>E-4 to E-3</u> GLO = 40 chains or 2640.00 Ft.	GLO = 40 chains or 2640.00 Ft.
"HUNTER HEIGHTS SUBDIVISION" + "SUPERVISOR'S PLAT NO. 5"	"THE WOODS OF ORCHARD LAKE SUBDIVISON NO. 1"
(Sec 8) = 2673.72 Ft. "SUPERVISOR'S PLAT NO. 5" (Sec 8) = 2673.72 Ft.	(Sections 8 & 9) = 2644.13 Ft. 2664.19 Ft. (GPS-MEA)
2668.65 Ft. (GPS-MEA)	7 20
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
E-4 I placed a 2" diameter brass cap stamped Oakland County R	emonumentation, PS #17623 on the existing 4" diame
Concrete Monument with 3/8" Iron Rod	-
N86°W 33.85' Set Mag Nail & Remon Washer NE face 29" Oak	\ab\$\$\$AEda
N03°E 13.87' Set Mag Nail & Remon Washer West face 20" Pine Due East 25.94' Set Mag Nail & Remon Washer South face 9" Pine	WHAT OF MISSIAN
S21°E 67.50' NW comer of block building	TATE OF MICHAEL
HISTON	
The selected location is accepted by me and is generally accepted by	Professional Surveyors as the Deat available evidence
the position of the oliginal corner	PROFESSIONAL SURVEYOR
l / / * *///	1-21 36 3 1700

Surveyor's Michigan License No.