

SURVEY &
REMONUMENTATION

APR 24 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:49

For corners in

Ottawa
(County)

Located in:
Robinson Twp.

Corner Code #

- | | | |
|------------------------------------|--------------------------|-------------------|
| 1. Public Land Survey | T <u>7N</u> R <u>15W</u> | <u>A-7</u> |
| | T _____ R _____ | <u>NE Corner</u> |
| | T _____ R _____ | <u>Section 19</u> |
| | T _____ R _____ | |
| 2. Property Controlling in Section | S _____ T _____ R _____ | |
| | S _____ T _____ R _____ | |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | |
| | S _____ T _____ R _____ | |

Deborah K. Kellerman
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Carl P. Englert, in a field survey on October 19, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-7 corner common to Sections 18 & 19
Original Gov't corner set may, 1832
by Calvin Britain

West bdry 78' N. of Post, Set corner to 18 & 19
Beech 14" North 15 Links
Beech 15" S42°E 38 Links

LCRC Liber 11, Page 73
(11/29/73)
A-7 Fd. Angle Iron
S.W. 24.64' 16" Maple
N.W. 34.27' P.P.
S.S.W. 98.61' T.P.
S.E. 63.09' St. Sign

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7 corner common to Sections 18 & 19

Found Angle Iron
Found G.H. corner South 51.36'
Found S.E. 63.' +/- St. Sign

P.A. 345 OTTAWA COUNTY

PEER APPROVED 12/12/94

Accepted as a careful and faithful perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7 Corner common to Sections 18 & 19

Set 3/4" x 3' long Steel Bar with O.C. Remon. Cap in Mon. Box 7' +/-
W. of Road E

O.C. Remon. Tag & Nail in N. side 16" Maple
O.C. Remon. Tag & Nail in N.E. side P.P.
O.C. Remon. Tag & Nail in E. side P.P.
O.C. Remon. Tag & Nail in S.W. side P.P.
O.C. Remon. Tag & Nail in S. side 15" Pine
T7N, R16W Corner

S69°W 85.86'
S85°W 85.98'
N43°W 126.63'
S71°E 36.38'
S65°E 79.30'
SOUTH 51.36'

Corner is 0.13' East of line between SE cor. 13-7-16 and the E 1/4 cor. 13-7-16.

Signed by Carl P. Englert Jr.

Date 12/11/94

Surveyor's Michigan License No. 18987

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN. 28, 1976
REVISED MAY 24, 1978
REVISED JAN. 1983

