

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC -8 PM 12:35

For corners in

Ottawa
(County)

Located in:
Robinson Twp.

Corner Code #

1. Public Land Survey T 7N R 15W E-13
T R SE Corner
T R Section 32
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

REGISTER OF DEEDS
OTTAWA COUNTY, MI
SURVEY &
REMONUMENTATION

JEC 65 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Carl P. Englert, in a field survey on November 18, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-13 corner common to Sections 32 & 33
Original Gov't corner Set 1831
by Lyon & Sibley

Liber 6, Page 77
Reset Cast Monument
West 63.66 to Olive Corner
N.NE. 78.20 to Nail W. Side 16" Poplar
N.E. 56.74 to Nail N.W. side 14" Oak
S.W. 94.33 to Nail & Tag N. Side P.Pole
N.W. 180.87 to Nail W. Side P.Pole

Set Corner
Pine 8" N50E 2.53 Chains
Do 10" N330W 1.21 Chains

(See back of page)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-13 corner common to Sections 32 & 33
Found 4" Harrison Cast Iron Mon. in Mon. Box
Found Olive Corner West 63.65'
Found P.P. S.S.E. 94.43'
Found T.P. (cut off) N.W. 56.94'
Found 10" Maple S.W. 76.10'

P.A. 345 OTTAWA COUNTY
PEER APPROVED 11/21/94

Accepted as a careful and faithful perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13 corner common to Sections 32 & 33
4" Harrison Cast Iron Mon. in Mon. Box
O.C. Remon. Tag & Nail in N.E. Side T.P. Stub
O.C. Remon. Tag & Nail in S.E. Side 20" Maple
O.C. Remon. Tag & Nail in W. Side P.P.
O.C. Remon. Tag & Nail in N.W. side 24" Maple
Centerline Top of Fire Hydrant
West 63.66' to Olive Corner

N530W 57.30'
S410W 76.64'
S 20E 94.79'
N510E 79.78'
N550E 54.70'

Signed by

Carl P. Englert

Date


11/21/94

Surveyor's Michigan License No.

18987

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 1975
REVISED MAY 1975
JAN. 1983

REMON LIBER 1 PAGE 504



Liber 2, Page 35

E-13 Set Cast Iron Mon. in Place of "T" Iron

P.P.	SSE	94.43'
24" Ash	SE	39.82'
8" Maple	NE	79.85'
Tel. Pole	NW	56.94'
10" Maple	SW	76.10'
6 St. Sign	SW	32.47'

SURVEY &
REMONUMENTATION

DEC 05 2000

Liber 6, Page 145

E-13

Raised C.I.M.

Fence Post NW 57.27'

8" Oak NE 56.73'

Triple Oak ESE 58.87'

Olive corner W 63.65'

SECTION