

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON Located In: Corner Code #
 (County)

1. Public Land Survey	T	<u>T49N</u>	R	<u>42W</u>	E-9
	T	_____	R	_____	_____
	T	_____	R	_____	_____
	T	_____	R	_____	_____
2. Property Controlling	S	_____	T	_____	_____
In Section	S	_____	T	_____	_____
3. Miscellaneous	S	_____	T	_____	_____
Property in Sec.	S	_____	T	_____	_____

**SURVEY &
 REMONUMENTATION**

MAR 23 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

Section Corner common to Sections 20, 21, 28 & 29, T49N R42W.

I, Earl W. Applekamp, in a field survey on March 31, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		19		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Burt, U.S. Deputy Surveyor, June 14, 1848.
 Set Sugar Post.

ORIGINAL BEARING TREES:

12" Sugar	S56°E	27.06'
12" Sugar	N49°W	13.86°

In 1957 MDOT indicates a 1" Iron Pin was in the center-line of Old Highway M-64. The surveyor accepted this as the corner and tied the New Highway M-64 to it. In 1971 I found the 1" Iron pin 3 feet below the surface and raised it with a 1" Pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The 1" Iron Pipe was still in the old road bed and has been used for several surveys in the area. I accepted the pipe as the only logical position for the corner.

Research on file with the Ontonagon County Remonumentation Program Representative.

FIELD GROUP APPROVED
Earl W. Applekamp
 COUNTY CLERK 5-11-99

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 5/8"x12" rebar with a 3" stamped cap into the pipe and drove both down 2" below the top of blacktop approach to Highway M-64. I established a reference monument, a 2 1/2"x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T49N R42W, S20, S21, S29, S28, R.M., 1999, P.S. 17610. I established three other bearing objects.

REF. MON.	N23°E	34.05'	- Nail in P. Pole	S10°E	214.33'
Nail in P. Pole	N16°E	174.50'	- Nail in 9" H. Maple	S78°W	152.01'



Signed by Earl W. Applekamp
 Surveyor's Michigan License No. 17610

Date May 10, 1999