SURVEY & REMONUMENTATION

8339

APR 2 4 1995

ROSCOMMON COUNTY REMONUMENTATION TO BE FILED IN LIBER 3 OF LAND

CORNERS

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 STATE OF MICHIGAN ROSCOMMON COUNTY RECORDED

For corners in

Roscommon

Lot No.

Public Land Survey

Property Controlling

COMMISSION Located In: Corner Code ##

T 22N R 3W

_. R

_ R

14 NOV 94 3:05 P.M.

ROBERT W. SMITH REGISTER OF DEEDS

ROSCOMMON COUNTY PEER GROUP APPROVAL MEM DATE _// - 10 - 94

__ R in Section __ T ___ Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

Private Claims Larry L. Cavanagh , in a field survey on October do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

13

on this certificate.

Description of original monument and accessories and/or subsequent restoration: Cedar Post set by William A. Burt 1849 1925 Emery City, Liber 2, Page 6

Cedar 16" N12°W 19 links

_ , Recorded Plat _

Cedar 6" N15°E 14 links

1920 Idlewild Resort

Liber 1, Page 52, Knapp

1921 Over The Top Resort

Liber 1, Page 54, Knox

Del aMater

1941 Henning Minutes of Survey

1944 Henning Section Subdivision Section 14 (metal monument in cor)

1946 R.T. Ostling Section Survey

Sections 15 and 16

Previous Minutes of Surveys by various surveyors 1946 to present, all using same location

Liber 2, Page 230 LCRC

1/2" Iron Rod in mon box

LCRC (1990) Cavanagh 1/2" Dia iron in Payt box P.Pole S40E 43.6 P. Pole N12W 81.45 P. Pole N57W 66.75 P.K. Nail N0°04'W 108.6 (1.05' W. of Sec Line)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found boat spike over top of boat spike in monument box

S40°E P. Pole 43.6 feet

PK nail N0°04'W 108.6 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 1/2" x 24" Cast Iron Roscommon County Monument

N13°E nail and tag in P. Pole 144.61 feet

\$40°E nail and tag in P. Pole 43.66 feet

878°W nail and tag in P. Pole 119.55 feet

N0°04'W P.K. nail in blacktop 108.54 feet

NOTE: I have made surveys tied to this corner over the post 25 years, checking previous surveys of record including the above mentioned plats, I believe the same location has been perpetuated from 1920.

Is accepted as the best available evidence of the position of the original corner.

17614

OF MICHIC LARRY L CAVANAGH PROFESSIONAL SURVEYOR No.

OFESSION

RVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

LIBER 3 PAGE 120