MAY 0 5 1995

M	RAAI	SSION
K 78 111	111111	Carried & Charles In

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 then 4 hate 170

For corners in			CIRCK T FAUL 15	
ST. JOSEPH Located In:		Corner Code ≠	STATE OF HICHIGAN ST. JOSEPH COUNTY	
MENDON TWP:			FILED	
1. Public Land Survey	T <u>5S</u> R <u>10W</u>	<u>L-5</u>		
	T R		12 APR 95 3:17 P.M.	
	T R	· · · · · · · · · · · · · · · · · · ·		
	T R		CYNTHIA JARRATT .	
2. Property Controlling	S T R		REGISTER OF DEEDS	
in Section	S			
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number	
Property in Sec.	S T R			

APRIL 9, 19 95 I, WAYNE A. MOSTROM , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-5

4. Lot No.

5. Private Claims

1877 SURVEY BY ANDREWS

SET +'D STONE @ MID POINT 8" MAPLE = \$71 1/4°E 1.36 1/4 CH 12" MAPLE = N73 1/4°E 1.44 3/4 CH POWER POLE = S49°E 44.77

ROAD COMMISSION - 1966

LARGE STO. IN MON. BOX RR RAIL = N2°E 26.18'

RR RAIL = \$47°W 37.41'

1976 LCRC IN 3/05 & MOSTROM SURVEY

NOTCHED STO, IN MON. BOX IN CL RDWY'S P.P. = \$45°E 45' I BEAM POST = NORTH 26.15' LCRC IN 2/257 (D. MOSTROM)

10

11

12 13

NOTCHED STO. IN MON. BOX TOP/S. FACE RR RAIL = N. 26.18'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: p.p. = \$50°E 45.081

FOUND NOTCHED STO. IN MON. BOX IN CL RDWY. TO S. & 1' N. OF CL OF E-W RDWY (NO FENCE RUNNING NORTH IN IMMEDIATE AREA) I BEAM POST = N2°E 26.18' OR NORTH 26.15' P.P. = SE 45' OR S50°E 45.08' 6" HICK. = \$45°W 50.1"

_____ , Recorded Plat __

SERVICE POLE = S29°W 64.761 8" HICK. = \$48°W 29.941 CL HWY. = N.1'

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 ON , APRIC 10 Way CO. REPRESENTATIVE , 19 95

C.	Description of monument	for corner and accessories	established to perpetuate	locating the position	of the could.
----	-------------------------	----------------------------	---------------------------	-----------------------	---------------

SET 5/8" X 10" LONG BAR WITH STD. CAP IN CONC. OVER STONE IN MON. BOX

> TOP/SOUTH FACE OF I BEAM POST = NORTH 26.15' N & W IN W. SIDE POWER POLE = S50°E 45.08' N & W IN W. SIDE SERVICE POLE = S29°W 64.76' N & W IN SE SIDE 10" HICK. = \$45°W 50.10'



Signed by <u>L</u> Surveyor's Michigan License No.

Date _

14100