

JAN 22 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ST. JOSEPH

(County)

Mendon Twp.

1. Public Land Survey

Located in:

Corner Code #

T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_  
T\_\_\_ R\_\_\_  
S 22 T 5S R 10W #0001  
S\_\_\_ T\_\_\_ R\_\_\_  
S\_\_\_ T\_\_\_ R\_\_\_  
S\_\_\_ T\_\_\_ R\_\_\_

LIBER 5 PAGE 131

STATE OF MICHIGAN  
ST. JOSEPH COUNTY  
FILED

28 DEC 1998 1:31:46 PM

CYNTHIA L. JARRATT  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, David W. Mostrom, in a field survey on Nov. 16 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

2 Mile post on the West side of Nottawaseepee Indian Reserve

\* GLO

Set Post

No witnesses provided

\* GLO

$\frac{1}{4}$  Corner common to Sections 22 & 27 is 2 links  
South of mile post

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found stone at  $\frac{1}{4}$  corner between Sections 22 & 27 (H-9) & excavated area 3' E-w x 3' N-S x 3' Deep North of stone - found no evidence of corner. Set 5/8" x 24" iron bar w/std. cap in mon. box 1.32' North of stone at (H-9) on projection of line from  $\frac{1}{4}$  corner common to Sections 27 & 34 and  $\frac{1}{4}$  Corner common to Sections 22 & 27.

RATIFIED BY PEER GROUP  
IN ACCORDANCE WITH P.A. 345  
ON Oct 12, 1998  
W. R. CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" x 24" iron bar w/std. cap in mon. box

$\frac{1}{4}$  corner common to Sections 22 & 27 - South 1.32'

Corner falls in  $\angle$  of Buchner Road & 3' North of  $\angle$  Clark Road projected to West

N & W 2.0' high in S. side of P. Pole = S85°E 20.76'

N & W 1.0' high in N. side of 34" Maple = N40°E 41.30'

N & W 1.0' high in NE side of P. Pole = N35°W 45.92'

N & W 2.0' high in N. side of P. Pole = S75°W 90.12'

Signed by

David W. Mostrom

Date November 19, 1998

Surveyor's Michigan License No. 32339

