

MAY 05 1995

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 4 PAGE 115

For corners in

ST. JOSEPH  
(County)

Located In:

Corner Code --#

STATE OF MICHIGAN  
ST. JOSEPH COUNTY  
FILED

4 APR 95 9:49 A.M.

CYNTHIA JARRATT  
REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

COLON TWP.  
1. Public Land Survey

T 7S R 9W

F-1

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, DAVID W. MOSTROM, in a field survey on MARCH 24, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

(F-1) NORTH 1/4 CORNER SEC. 4 T7S, R9W

GLO - NOT SET

1964 ROAD COMMISSION

1/2" PIPE IN MON BOX, RE-ESTABLISHED

39" MAPLE = N38°E 88.40'

25" SYCAMORE = S50°E 101.66'

SOUTH 1/4 COR. SEC. 33 T6S, R9W = EAST 81.57'

1975 CORNER RECORD IN BOOK 3, PG 91

BOX &amp; PIPE

TRIPLE MAPLE = SE 69.05'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F-1)

FOUND 1/2" PIPE IN MON. BOX IN CL OF E-W ROAD

48" MAPLE = N38°E 88.40'

SOUTH 1/4 COR. SEC. 33 T6S, R9W = EAST 81.54'

RATIFIED BY PEER GROUP  
IN ACCORDANCE WITH P.A. 345  
ON MARCH 13, 1995  
David W. Mostrom CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F-1) NORTH 1/4 CORNER SEC. 4 T7S, R9W

SET 5/8" X 24" IRON BAR W/STD CAP IN MON. BOX IN PLACE OF 1/2" PIPE

SOUTH 1/4 COR. SEC. 33 T6S, R9W = EAST 81.54'

N &amp; W 4' HIGH IN SW SIDE OF 12" MAPLE = N23°W 39.65'

N &amp; W 3' HIGH IN SW SIDE OF 40" MAPLE = N18°W 81.18'

N &amp; W 4' HIGH IN W SIDE OF 8" ANCHOR POST = SOUTH 32.98'

N &amp; W 4' HIGH IN NE SIDE OF 8" MAPLE = S37°E 52.21'



Signed by

Date

MARCH 24, 1995

Surveyor's Michigan License No.

32339

REMONUMENTATION