

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

DATE 7/12/96 LAND CORNER RECORDATION CERTIFICATE

For corners in

Schoolcraft
(County)

Located In:

Corner Code #

1. Public Land Survey

T42N R 15W

G-9

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Received & Filed this 8th day of
October 19 96 at 11:29 AM

Sigrid I. Hedberg
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

I, Thomas P. O'Brien in a field survey on August 14, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-9 (Section Corner common to sections 21, 22, 27 and 28)
Sept. 18, 1850 Algernon Merryweather D.S. set corner post.
Sugar 12 in. S64E 37 links Beech 4 " N52W 31"

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

SURVEY &
MONUMENTATION

DEC 16 1996

COMMISSION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9 June 30, 1983 Donald R, Schofield, R.L.S. Recovered 1/2" iron with cap as noted Liber 1 page 324.

August 14, 1996 Thomas P.O'Brien PS Recovered iron bar with illegible cap in center line of county road @ intersection of fence line to the East. The corner position as recovered has been used in previous surveys of record. Reset with IB in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9 Set 18" Iron Bar with ID cap in monument box.

Witnesses: GTE riser with hole in top S26°W - 88.73'
Fd. Power Pole - S58°E - 33.17' (M)
Fd. M.B.T. Pole - N8°W - 139.40 (M)
Fd. Service Pole - N72°E - 127.31'
Set Cedar Post - West - 33'



Signed by Thomas P. O'Brien

Date August 14, 1996

Surveyor's Michigan License No. 21274

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1993

LIBER 4 PAGE: 46