

SCHOOLCRAFT COUNTY PEER GROUP APPROVED

DATE 10/15/97 LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

JAN 21 1998

SECTION

For corners in

Schoolcraft
(County)

Located in:

Corner Code #

- | | | |
|------------------------------------|-------------------------------------|-------------|
| 1. Public Land Survey | T <u>42</u> N <u>16</u> W | <u>I-12</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling in Section | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |

4. Lot No. , Recorded Plat
5. Private Claims

Thomas P. O'Brien, in a field survey on Oct. 31, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Received & Filed this 9 day of
Dec 1997 at 2:45 PM
Sigrid I. Hedberg
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- I-12 E 1/4 Corner Section 34
Aug. 13, 1850 - Algernon Merryweather D.S. set qr. section post.
Birch 14 in. S23E 17 lks. Hemlock 4 in. N71W 8 lks.
June 5, 1975 - Thomas P. O'Brien P.S. recovered a " 1/2" bar @
fence corner N + S, E. LCRC recorded Liber 1, page 158.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- I-12 Oct. 31, 1997 - Thomas P. O'Brien P.S. recovered a 1/2" iron pipe with R.L.S. cap # 11368, fd. 3/4" iron pipe and 3/4" iron rod 4' long. Witnesses found verify 1/2" iron pipe with R.L.S. cap # 11368 to be corner position as found by O'Brien on June 5, 1975. Replaced iron pipe with Schoolcraft County Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- I-12 Schoolcraft County Monument stamped to identify.

Witnesses: (Fd.) 6" Maple - N78°E - 19.65'
(Fd.) 8" Maple - N56°W - 7.10'
NBT 4" W.Pine - S41°E - 17.40'
NBT 6" Maple - S71°W - 28.80'
4" Cedar Post - North - 1.0'



Signed by Thomas P. O'Brien P.S.
Surveyor's Michigan License No. 21274

Date November 28, 1997

LIBER 4 PAGE: 126