

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for sections 19/20

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-7-61

WITNESSES TO CORNER..... 16" Tamarack ($\frac{1}{4}$ S NBT) N67°E 82 links



12" Cedar ($\frac{1}{4}$ S NBT) S29°E 87 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners. Blaze on down stub near, no other evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 2, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler