NOV 1 0 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 NOV -6 PM 2: 38

For corners in			REGISTER OF DEEDS
Shiawassee (County)	Located in:	Corner Code #	Gayer Steeddan SHIAWASSEE COUNTY, MICH.
Public Land Survey	T_6NR_4E TR TR	_M-10	,
Property Controlling In Section Miscellaneous	STR STR ST_R		
Property in Sec.	STR		Register of Deeds Stamp & File Number
4. Lot No 5. Private Claims	, Recorded Plat		

I, Mark L. VanRaemdonck, in a filed survey on March 30, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - Original Joseph Wampler, D. S.

1823

Mon: Wood Post

Access: B. Ash 9 S54W 21 LKS

Beech 12 N10W 15 LKS

2. Mark L. VanRaemdonck, L. C. R. C.

Rec. L2, P727, August 17, 1990

Mon: Set Rerod and Cap #24622 using proportional measurements on line between the Northeast corner of Section 25, T6N-R4E and the Southwest corner of Section 30, T6N-R5E.

Access: West 40.381 Set N&T E. face

50.15' Set N&T N. face 12" Ash S50°E

S20°E 150.27' Delta Rerod

3. Mary A. Barnwell-Dwyer, Unrecorded survey dated 11/04/92

Mon: None Given Access: None Given

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found Rerod & cap #24622 as referenced in No. 2 above and is accepted as a careful and faithful re-establishment of the position of the original corner. This location was found to haven been set on the standard Township line at mid point between corners M-9 and M-11. Found no conflicting evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner

Installed a standard Shiawassee County Harrison Marker, stamped "Remon 24622" at the location described above. The marker is witnessed by the following


Set N&T #24622 in S. face 12" Ash \$85°W 40.81 Top Cen. N. end 18" CMP Culv. Top Cen. N. end 36" CMP Culv. \$80°E 24.11 52.87 \$20°W Top Cen. S. end 36" CMP Culv.

24622

Surveyor's Michigan License No.

Date <u>OCT. 29</u>, /997

M APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983



31001

APPROVED

County Remonumentation Peer Review Group

