SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

1994 REMONUMENTATION PROGRAM

	LAND CORN	ER RECORDATION CERTI	FICATE	R ≤ 9. ∃ ⊑ ₹
For corners in Arbela T	Filing Requir	rement of Act 74, Mich. P.	A. 1970	H DER HARGI TUSS REGI
Tuscola (County)	Located In:	Corner Code ##		STEEL NO.
Public Land Survey	T <u>lon</u> R <u>7E</u> T R T R	M-7		PAGE NO. PAGE NO. PAGE NO. PAGE NO. PH 4: 26 M. MCLAREN A COUNTY OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R S T R	, i	Register of De	eds Stamp & File Number
A 3 - 1 3 2 - 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
4. Lot No, Re 5. Private Claims			A B C	DEFGHIJKL
J. Filvate Glains			2 6	-5-4-3-2
Kenneth D. Dunton	in a field account on Atto	ust 6	4 7 7 5 5	- 8 - - 9 - 10 1 1 - 1
do hereby certify that under require lines 1 and 2 above were in courrent manual of survey instruct Management or by a decree of a Cabove were in conformance with Court of Law; established, reexpressed below: NOTE: Not more than 4 coron this certificate.	conformance with regulations at tions of the United States Depar Court of Law and/or that the corn the rules of the Michigan Board established, monumented, re-	nd rules therefore as required in rtment of the Interior, Bureau of L er points mentioned in lines 3, 4 a of Land Surveyors or by a Decree monumented, recovered, found	n the and 7	29 28 27 26 2 32 33 34 35 3
A. Description of original mo	anument and accessories an	d/or subsequent restoration:	13	
1821 G. L. O. Notes Joseph Wampler, D. S Set post cor. Section 13 & 24 Beech 14 N86E 22 Ash 17 S69W 10	ons by NW co Pine ?	28, 1886 Teskey, Surveyor rner Sec. 3, T10N-R8E N 56 3/4 W 107 d 5 N 24 1/2 W 132	Aug. 22, 1888 John A. Teske - stateme "See notes for	ey, Surveyor ent -
Section A continued	on back of this for	m.	•	
B. Description of corner evid	dence found and/or method	applied in restoring or reesta	blishing corner:	,
This iron appears to Beginning on May 24,	, 1978 I accepted for	box. n of iron by stones f und iron by stones as Teskey as the proper	corner locati	ion referred
C. Description of monument	for corner and accessories	established to perpetuate loc	ating the position o	f the corner:
& brass cap in conce S37°19'W 55.17' four S45°25'W 45.71' four N61°55'W 78.18' four N43°42'E 76.99' four N00°04'35"W 152.68'	rete in mon. box. Sind p. k. nail in NW : nd 1/2" rod & cap #1. nd spike in South fand p. k. nail in NW : found 1/2" re-rod in	1192. ce 24" oak.	cap, corner M	M-7, TION-R7E.
<i>11</i>	~ 1.05	· · · · · · · · · · · · · · · · · · ·	,	KENNETH D. * 1 DUNTON LAND
a (a	4-21/11	Doto	November 7.13	94 SUBVEYOR E

23503

Surveyor's Michigan License No. ___

```
Section A continued:
Feb. 24, 1964 Witness card by R. J. Black #3384.
Found 5/8" rod in place.
S45°W 40.25' to corner fence post.
N80°W 75.90' to nail in 24" oak.
N40°E 58.5' to tele. pole.
April 20, 1972 Survey by Gerald R. McKelvey, L. S. #19001 & recorded in Liber 1 of Surveys on Pages 421, 422, & 423 Tuscola County records. Survey refers to L.C.R.C. form Liber 1,
Page 18, Arbela Township records.
April 20, 1972 Land corner rec. certificate, Liber 1, Page 18, Arbela Township, by G. R.
McKelvey, L. S. #19001. Found 1/2" re-rod at center section of Vassar and Barnes Road.
North 71.78! North leg of road sign.
Southwest 49.49' center stop sign post.
Northwest 76.74' surveyor's disk in 18" chestnut tree.
October 19, 1977 Land corner rec. certificate by K. D. Dunton, L. S. #23503 & filed on Page
61, Arbela Township. Found very old 24" iron bar (bent) next to large stone & surrounded by
small stones 2' deep.
Set p.k. in asphalt over point.
N20°E 12.82' fnd. 1/2" re-rod by others.
S70°W 37.06' nail & flag in t.p.
S60°W 31.31 cntr. wood fence post.
N60°W 78.48' R.L.S. #11192 tag in 24" oak.
   Note: Iron 12.82' NE of this iron has been used by at least 3 other surveyors, as the
           SE cor. of Sec. 13. I believe this recent find to be original cor. and am recording
           this for general information only. I am at this time holding prev. corner as SE
            cor. Sec. 13. (recorded in Liber 1, Page 3)
May 24, 1978 Survey by K. D. Dunton, L. S. #23503 with Rowe Eng., Inc. and recorded in Liber 488 on Pages 881, 882 & 883, Tuscola County records. P. k. nail over iron rod next to st
N20°E 12.82' fnd. 1/2" re-rod by others.
S70°W 37.06' nail & flag in t.p.
 S60°W 31.3' cntr. wood fence post.
N60°W 78.48' R.L.S. #11192 tag 24" oak.
May 9, 1979 Survey by Charles S. Getz, L. S. #25843 with Kay Engineering & recorded in
Liber 498 on Page 182. Found 1/2" square iron. Accessories same as Survey Liber 488, Pages
 881, 882 & 883.
 April 28, 1989 Survey by K. D. Dunton, L. S. #23503 & recorded in Liber 595, Page 89,
 Tuscola County records. Found 1/4" sq. rod.
 N45°E 77.0' p. k. nail in p. p. N10°E 13' fnd. iron in N-S pave. centerline
 S35°W 55.2' p. k. nail in p.p.
 East 4' N-S centerline of pave.
 May 10, 1991 Survey by Lloyd D. McGinnis, L. S. #18999, with Wade-Trim/Edmands and recorded
 in Liber 614 on Pages 866, 867 & 868, Tuscola County records.
 Found 1/2" bar.
 W.N.W. 77.36' to nail in 24" chestnut.
        67.54' to p.k. in u. pole.
         65.35' to p.k. in u. pole.
 N.E.
 S20°W 12.87' to 1/2" square iron.
 June 10, 1991 Field notes from T.C.R.C.
 Found rod by stone at corner M-7, T10N-R7E
 NOO°15'25"E 152.68' found iron at apparent cor. A-7, TlON-R8E
 N20°56'00"E 12.85' found 1/2" rod prev. used as M-7, TlON-R7E
 South 2631.111 found iron at corner M-8, TION-R7E
 Aug. 30, 1991 Survey by Paul H. Brown, L.S. #33134, with Rowe Engineering, Inc. & recorded in Liber 619 on Pages 1048 through 1055, Tuscola County records. Found square iron rod
 in mon. box, 4.4' W. & 4.9' N. of centerline-centerline.
North 152.66' SW cor. Sec. 18, TlON-R8E, rod in mon. box.
 $30°W 55.19' fnd. p.k. in W. face p.p.
 S75°E 24.81' W.N.W. face 2" galv. str. sign post. N45°E 76.98' fnd. p.k. in N.N.W. face p.p.
                                                                 Section 13, T10N-R7E
    Section 24, TION-R7E
                                                         1821 Wampler 2640'
             1821 Wampler 2640'
1886 Teskey 2632.08'
                                                         1888 Teskey 2624.82'
                                            <u></u>
                                                         1989 Dunton 2683.33 to
             1978 Rowe 2631.11'
                                                         property controlling cor. Nelan M-6
             1979 Getz 2631.11'
                                                          1994 Dunton 2633.81'
             1994 Dunton 2631.11'
                                                                                          M-6
                                             M-7
  M-8
                                             <u>- 1</u>
                                                             Township Line
                                      1994 Dunton
                                                                                     Sec.18,T10N-R8E
                                              152.68
                                                          Apparent cor.A-7,T10N-R8E.Fnd.1/2"rod in mon.bo:
```

Section 19,T10N-R8E