NOV 1 5 1994

LIBER 4	ARMISSION
---------	-----------

## LAND CORNER RECORDATION CERTIFICATE

PP H9 EF P P VON

Filina	Requirement	of Act 7	4 Mich	PΔ	1970	

	r corners in Hartford T	Filing Require	ement of Act 74, Mich. P	P.A. 1970	2.00
	Van Buren County	Located In:	Corner Code ##	Mark Comits	<b>!</b>
1.	Public Land Survey .	T 3S R16W	B-11		10SURVEY
	S¼ Post Sec 30	T R T R T R	-		-
2.		T R T R			0101
3.		T R T R		Register of Deeds Stamp & File Number	17.0
4.	Lot No, Record	ed Plat			7991
5.	Private Claims			2 6 5 4 3 2	_ -
	Donald R Gilchri	et 1º	1/2/94	3	 12

GII CIII a lielo survey on \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Gov.Wit. of 1830: Set % post at 40 ch.; 11" Beech S 23° W 5 lk.; 20" Beech N 61° W 20 lks. April 10, 1870, A.J. Pierce, CS, noted both wit. stumps removed. Put down good stake. In the 1940's & 50's T.A. Smith, CS, & W.Q. Smith, CS, both show distance to cor. at 2635.34'. In 1990 G. Mitchell fd. 1" pipe & Measured 2634.08' to SE corner; SE cor. Garage NW 144.8'; C/L road N 2'. On 6/23/92 J.C. Hunt fd. 5/8" iron in C/L gravel rd.; Survey

recorded in SE cor. Liber 9 pg. 347.

At meeting of Peer Group on 10/21/92, approval was given to re-set corner.

On 10/22/92, fd. 5/8" I.R. in centerline of gravel road as noted above.

Harrison Marker set, after 5/8" iron removed.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

10/18/94 D.R. Gilchrist, C.S., fd Harrison Marker paved over last year. Set mon. box over. Approved at the 11/2/94 Van Buren County Peer Group Meeting and is accepted as a careful and faithful perpetuation of the position of the Original Government Corner.

> Ratified by Peer Group in accordance with P.A. 345 of 1998 Yan Buran County Surveyor KHIKKW

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Fd. Harrison Marker, set Mon. Box over. N 05° W 47.40' nail E face 10" dia. Apple S 35.73' nail E face twin 12"-8" d. tree N 80° W 141.19' C/L tel. cable box S 80° E 141.56' C/L tel. cable box N 50° W 144.20' SE cor. garage Measured dist E 2634.08'

OF MICHIGA DONALD R. GILCHRIST PROFESSION No. 13583 OFESSION

Date