

SURVEY & REMONUMENTATION

APR 24 1995

COMMISSION

1994 Alcona County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County
Remonumentation
Liber 1 Page 700

For corners in

Alcona
(County)

Located In:

Corner Corner #

- | | | |
|------------------------------------|---------------------------|------------------|
| 1. Public Land Survey | T <u>25</u> N R <u>9E</u> | I-1, J- |
| | T ___ R ___ | |
| | T ___ R ___ | |
| | T ___ R ___ | |
| 2. Property Controlling in Section | S ___ T ___ R ___ | <u>Other #13</u> |
| | S ___ T ___ R ___ | |
| 3. Miscellaneous Property in Sec. | S ___ T ___ R ___ | |

APPROVED LAND CORNER
 P.A. 345 of 1990
 ALCONA COUNTY
 Date: 12-21-94
 County Rep E.T.L.

RECORDED

DEC 21 2 08 PM '94

Janis A. Smith
REGISTER OF DEEDS
ALCONA COUNTY, MICHIGAN

E. J. L.
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

David B. Guthrie in a field survey on December 14, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1839: G.L.O. Survey by Lewis Clason - Set Post and Referenced
 B.Oak 14 - S58W - 25 / B.Oak 09 - N49W - 14

1955: Survey by James L. Scott - Set Concrete Monument

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found Square Concrete Monument S.E. corner of Lot 1 of the Plat of Huron Palisades.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: placed a 5/8" Iron Rod with a 3" Aluminum Cap stamped to identify the Corner.
 Referenced -

- S85°W - 24" W.Pine - 12.02 Feet
- N10°E - 6" Oak - 8.45 Feet
- S35°E - 12" Cedar - 11.95 Feet
- N12°W - 12" R.Pine - 62.40 Feet
- N25°E - 1/2" Iron Rod - 59.9 Feet



Signed by *David B. Guthrie* Date 12/19/94
 Surveyor's Michigan License No. 22435