

1994 Alcona County Remonumentation Corner

Alcona County
 Monumentation
 1 Par 107

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corners in

Alcona
 (County)

Located In:

Corner Code

- 1. Public Land Survey T 25N R 9E
 T _____ R _____
 T _____ R _____
 T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

I/J-11 (M)

#015

APPROVED LAND CORNER
 P.A. 345 of 1990
 ALCONA COUNTY

Date 12-28-94
 County Rep. E.T.L.

DEC 28 10 05 AM '94

David A. Guthrie
 REGISTER OF DEEDS
 ALCONA COUNTY MICHIGAN

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	13	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

David B. Guthrie in a field survey on December 27, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: G.L.O. Survey by Mullett & Burt - Set Post and Referenced
 Y.Pine 14 - S62W - 31 / Y.Pine 12 - N34W - 37

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Set a 5/8" Iron Rod at the average mean bearing between the North Line of Section 26 and the South Line of Section 35.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: Replaced with a 5/8" Iron Rod with a 3" Aluminum Cap stamped to identify the Corner.
 Referenced -
 N60°W - 8" Tamarack - 61.76 Feet
 N23°E - 6" Tamarack - 37.04 Feet
 N52°E - 6" Cedar - 35.65 Feet
 S37°W - 15" W.Pine - 92.24 Feet



Signed by David B. Guthrie Date Dec. 28, 1994
 Surveyor's Michigan License No. 22435