

SURVEY & REMONUMENTATION

FEB 19 1998

05-54

Approved by _____ of County
Land Surveyors' Remonumentation
Peer Group, Mich. Act 643 of
P.A. of 1990 On 12-10-1997

Donald W. Kinnunen
Chairman

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in _____

County

Located In: _____

Corner Code # _____

1. Public Land Survey	T	<u>48</u>	R	<u>15</u>	<u>C1</u>
	T	<u>49N</u>	R	<u>15W</u>	<u>C13</u>
	T	_____	R	_____	_____
	T	_____	R	_____	_____
2. Property Controlling in Section	S	_____	T	_____	_____
	S	_____	T	_____	_____
3. Miscellaneous Property in Section	S	_____	T	_____	_____
	S	_____	T	_____	_____

FILED
TIME 8:30 A.M.

DEC 17 1997

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1					
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					
13											

I, Robert L. James, in a field survey on 12-10-1997, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C1: PLS - John Burt, OS, 1841 * Set post corner of Sections 5 and 6 * White Pine 15, N.40 E., 7 links * White Pine 16, N.25 W., 26 links **** George E. Adair, OS, 1851 * White Pine 28, S.45 E., 59 links * White Pine 24, S.18 W., 29 links **** Dean C. DeLaMater, SLS, Michigan Department of Conservation, 1953 * Established corner position from 4 original BT's still in place, 1 in fair condition, 3 in poor conditions * Set 1 inch pipe w/ 4 inch brass cap * Made the following witness's - White Pine stump 28, N.23 W., 55 links * White Pine stump 36, S.10 E., 73 links * Recorded in Liber 1, Page 39, Alger County records. **** No other subsequent restoration on record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C1: Found 1 iron galv. iron pipe w/brass cap * Located original BT positions and found 3 stumps of the 4 originals * Recovered both BT's from the 1953 report - White Pine stump in the Southeast position in poor condition and White Pine stump in the Northwest position badly decayed * Established 4 reference trees * Monumented position as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C1: Exist. 1 inch galv. iron pipe w/brass cap as stamped to identify corner position. Corner lies approx. 100 feet South of a East-West track road * Established the following reference trees w/BT signs, blazed, scribed and painted. Set PK nails for measure w/Alum. I.D. washers in the following - Red Pine 8, S.75 W., 26.67 feet, '36 BT' * Maple 5, N.56 W., 13.43 feet, '32 BT' * Red Pine 8, N.13 E., 13.66 feet, '32 BT' * Red Pine 7, S.07 E., 6.93 feet, '35 BT' * Survey marker sign on 6 foot steel post, S.35 W., 1.0 feet * All bearings are magnetic.

Signed by Robert L. James
Surveyor's Michigan License No. 25849

Date 12/10/1997

