

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Arenac
(County)

Located In

Corner Code #

1. Public Land Survey T _____ R _____
T _____ R _____

2. Property Controlling in Section S 30 T 20N R 3E 6
S 30 T 20N R 3E 8

3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on June 20, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1	6	5	4	3	2	1							
2	7	8	9	10	11	12							
3													
4	18	17	16	15	14	13							
5													
6	19	20	21	22	23	24							
7													
8	30	29	28	27	26	25							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - None

8 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

6 - NE 1/16 Cor., Sec. 30 - Set stamped 2" Alum. Cap on 5/8" x 34" iron rebar per Standard BLM procedure.

8 - CW 1/16 Cor., Sec. 30 - Set stamped 2" Alum. Cap on 5/8" x 34" iron rebar per Standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
Set Blue Carsonite Post with loc. tag 1' SW
S84°E 3.30' to set N & T in N. side 10" R. Maple
S42°W 13.95' to set N & T in E. side 8" R. Maple
N33°W 42.79' to set N & T in NE side 9" R. Maple
S52°E 8.97' to set N & T in N. side 8" Elm

8 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar.
Set Blue Carsonite Post with loc. tag 1' SE
N16°E 39.18' to set N & T in NW side 4" W. Pine
S80°E 13.05' to set N & T in N. side 6" Oak
S2°W 26.76' to set N & T in W. side 8" Oak
S38°W 12.17' to set N & T in NW side 6" R. Maple

Signed by:

Craig W. McVean

Surveyor's Michigan License No.:

39088

Date:

11/30/2005