

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Arenac
(County)

Located In

Corner Code #

1. Public Land Survey T 20N R 3E B11
 T R

2. Property Controlling
in Section S T R
 S T R

3. Miscellaneous
Property in Section S T R
 S T R

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on June 14, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

B11 – GLO – Set 1/4 Post – J. Mullett – 1846

 Spruce 6" S41°W 6 L.

 Spruce 6" N33°E 21 L.

 - CCC Notes – 1930's – Random
 Line E.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B11 – 1/4 Corner common to Sec. 30 & 31 – No GLO evidence found. Set 4" DNR Alum. Cap on 1" x 36" Galv. iron pipe by single proportion to GLO between 'A11' and 'C11'. N-S single strand wire is 27' E. Single strand goes East 82' ± S. DNR Mon. accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B11 - 4" DNR Alum. Cap on 1" x 36" galv. iron pipe

 Set Blue Carsonite Post 1' SW

 S50°W 12.86' to set N & T in SE side 5" R. Pine scribed 'XBT'

 S5°E 7.99' to set N & T in W side 5" R. Pine scribed 'XBT'

 N27°E 20.12' to set N & T in W side 12" R. Pine scribed 'XBT'

 S68°E 34.04' to set N & T in N side 12" R. Pine scribed 'XBT'



Signed by: Craig W. McVean

Date:

9/22/2005

Surveyor's Michigan License No.: 39088