

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In: Corner Code #

1. Public Land Survey	T 44N R 1W	J8
	T _____	_____
	T _____	_____
	T _____	_____
2. Property Controlling in Section	S 21 T 44N R 1W	16
	S _____ T _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____	_____
	S _____ T _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

16 Jul 09 2003
 J8 Jul 08 2003

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2			1	
3													
4	7		8		9		10		11			12	
5													
6	18		17		16		15		14			13	
7													
8	19		20		21		22		23			24	
9													
10	30		29		28		27		26			25	
11													
12	31		32		33		34		35			36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(J8) Center of Section 23. Not established in the original survey.

(16-Sec. 21) East 1/16 corner between Sections 21-28. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J8) Established the corner at the intersection of straight lines connecting opposite Quarter corners, all of record. The corner established falls 3' East of and 10' South of the intersection of the centerlines of ditches South and West.

(16-Sec. 21) Found and accepted a PK nail with a brass tag midway and on line between Section corner to the east and Quarter corner to the west. Replaced the PK nail with a monument as described below. The corner falls in the centerline of Hwy. M-48.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J8) Set 1" IDX36" I.pipe with 4" alum. MDNR cap. Set measuring nails with plastic tags in:	(16) Set 1/2" dia. rebar with plastic cap "MICH DNR PS 33986". Blazed, scribed, and set measuring nails in:
10" Tamarack S29E 82.8'	10" Tamarack N70E 111.4' "E1/16 8T"
20" Spruce S20E 99.05'	6" Balsam S08W 60.6' do
5" Willow N36W 19.8'	6" Balsam S61W 104.95' do
Wooden fence post N12E 79.2'	10" Spruce N46W 103.8' do
Bearings are magnetic. Distances are to nail with tag.	Bearings are magnetic. Distances are to nail with tag.



Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 7/29/03

For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1985