

SURVEY &
REMONUMENTATION

SEP 12 1995

LAND CORNER RECORDATION CERTIFICATE
COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

95 AUG -4 AM 9:16

Charlene M. Peckham
REGISTER OF DEEDS

For corners in

Charlevoix (County)	Located In:	Corner Code #
1. Public Land Survey	T 32W R 5W	B-1
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Wayne E. Boss in a field survey on May 1, 1995, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Set qr. Section post
1. Hemlock 20 N80 E 16
2. Hemlock 16 N56 W 42
John Mullett, May 1840

Fd quarter post
2. Old BT. Hemlock 16" N56W 42Lks
3. New Hemlock 28 S11½W 6 lks
EK Robinson, July & August 1882

3. Fd. Old 1/4 post stake hole
Set new post iron pipe 1"x36"
and cedar Post in Pit
E.A Robinson Dec 1913

2. Old BT. Hemlock 16" N56W 42 Lks
3. New Hemlock 28 S11½W 6 lks

Fd. 1" pipe and added DNR Mon
and Cedar Post
4. Power Pole N86° W41.07
5. 1/2" Pipe at P.P Anchor
S26° W 26.20
6. Fence corner E-S and
Nwly at of of 25' bluff SE-NW
LCRC 6, L.2, Pg. 6
Set by Carl Roser, Jan 1975

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DNR Mon Fd

4. Fd Tag PP N86°W 41.45
7. Fd Tag Fence Post N5°E 49.35
8. Fd Tag Fence Post S85°E 45.71

GLO to A-1 = 2682.9 EXR 1888 = 2644.6
GLO to C-1 = 2640 EAR 1913 = 2630.4

Roser 1975 = 2667.9
Roser 1975 = 2634.3

Charlevoix Co. Surveyor
APPROVED
Signature Mary C. Feinoldt
Date: ~~Aug~~ July 20, 1995
PA 345 of 1990

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-1 DNR Mon Fd

4. Fd Tag PP N86°W 41.45
7. Fd Tag Fence Post N5°E 49.35
8. Fd Tag Fence Post S85°E 45.71
9. Set spk Fence Post S10°E 2.77

And is accepted as a careful and faithful perpetuation of the position of the original corner.



Recorded by *[Signature]* Date July 28, 1995

Surveyor's Michigan License No. 20703

LIB# 002 PAGE 384