

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>33</u> N. <u>5</u> W.	<u>I-12, J-13,</u>
2. PROPERTY CONTROLLING IN SECTION <u>35</u>	T. <u>33</u> N. <u>5</u> W.	<u>3</u>
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 8, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 3 Etab. SW cor of N1/2-NW1/4 of Sec. 35, midway & on line bet. Sec. cor. to N & 1/4 cor. to south.
- I-12 Reestab. East 1/4 cor. Sec. 34, equidistant & on line bet. NE cor. & SE cor. of Sec. 34.
- J-13 Reestab. S1/4 cor. of Sec. 35, 25' south of end of old crooked N-S fence to N (which fits midway bet. SE & SW cor's of Sec. 35) and in approx. avg. ctr. of E-W gravel rd. This alignment fits approx. split of E-W R.O.W. fn's at location of approx. E1/8 cor. 1/4 mile to E and fits approx. ctr. of rd. to S, south of position of W1/8 cor. 1/4 mile to West. E.A. Robinson survey in 1906 (W1/2 of north line of S-2, 32-5) indicates Ced. Stk. in culvert (rd. in place) & E.A.R. sur. in 1924 (E1/2 of S line of S-35, 33-5) says "from 1/4 post on E. edge of culvert". Ctr. of present newer 18" C.M.P. culvert is 2'± West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

	3	I-12
Drove 5/8" x 36" rerod w/RLS cap & set ced. post w/loc tag.	Set DNR mon & Ced. Post	Set 7/8" x 18" solid ir. (buried 0.5)
8" Maple N85°W 15.8	6" Maple N60°E 21.6	10" Tamarack N60°W 50.7
7" Elm N10°W 16.7	5" Maple N25°W 12.0	P. Pole S40°E 46.43
9" Maple N74°E 13.0	7" Maple S40°W 53.2	7" Cedar N30°W 30.6
N-S fn. remains (3 std. B-W down) West 102'±	N-S fn. remains (3 std. B-W w/posts, down) West 53'±	18" Culvert West 2'
E-W fn. remains (3 std. B-W, down) North 295'±		Set ced. post N 33'

SIGNED BY Carl F. Roser 01-12-82 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY