

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


DELTA COUNTY
T 43 N R 22W

DESCRIPTION OF CORNER West 1/16 for Sections ¹⁹/₃₀

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED May 10, 1972

WITNESSES TO CORNER..... 8 Cedar (W 1/16) (MBT) N50°E 47.4'



12 B. Spruce (BT) S45°W 74.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportions and on line between the section corner to the west and 1/4 corner to the east. The corner lies on the east side of the north-south road and north of the road from the west.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

6-19-72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68