

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ⁴² NR. 27 W.

Dickinson

----- COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 6 and 7

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 12" S 85 E 13 links, marked 1/4 S NBT

Cedar 16" N 53 W 28 links, marked 1/4 S NBT

Cedar 5" S 64 W 32 links, marked 1/4 S NBT

Distances measured from center of brass cap to NBT notch

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced from two original tamarack bearing trees, one in excellent condition and one in good condition.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 25 April 1957 with Clarence R. Ryberg.

SURVEYORS SEAL

Henry S. Peterson
SIGNED Henry S. Peterson DATE 4/26/57
REGISTERED LAND SURVEYOR