

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	(DICKINSON COUNTY) LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 43 N. R. 29 X W.	#F-9 & G-9
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. S. R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S. R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner F-9 (1/4 corner between Sections 21 & 28, T43N, R29W):
 Cedar post (Not found. No subsequent monuments found.)
 Y. Birch 6 S36E 12 (Not found. No subsequent accessories found.)
 Cedar 6 N78W 6 (Not found. No subsequent accessories found.)

Corner G-9 (Section Corner 21, 22, 27 & 28, T43N, R29W):
 Cedar post (Not found. No subsequent monuments found.)
 Y. Birch 20 N27W 13 (Not found. No subsequent accessories found.)
 Cedar 12 S61E 43 (Not found. No subsequent accessories found.)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner F-9: Restored 12-20-79 on line between Section Corners 39.900 ch. to E and to W.

Corner G-9: Restored 12-19-79 at record distance of 80.000 ch. N of Sec. Cor. 27, 28, 33 & 34 and at record distance of 79.800 ch. E of an original corner at Sec. Cor. 20, 21, 28, & 29. Position meets the original field note calls to ascend from post when going N and E, for the distance to a hilltop 4.00 ch. N, to a stream crossing 19.80 ch. W, and to a stream crossing 15.50 ch. S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner F-9: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
 B. Spruce 8 S52°W (mag.) 22.8 ft. "1/4S, NBT"
 B. Spruce 6 N76°E (mag.) 2.5 ft. "1/4S, NBT"
 W. Birch 6 N 7°W (mag.) 4.1 ft. "1/4S, NBT"
 Declination 2° 45' West.

Corner G-9: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
 Sugar Maple 20 S48°E (mag.) 30.6 ft. "S27, NBT"
 Sugar Maple 8 N25°W (mag.) 29.3 ft. "S21, NBT"
 Sugar Maple 6 N73°E (mag.) 23.2 ft. "S22, NBT"
 Balsam 8 S29°W (mag.) 7.2 ft. "S28, NBT"
 Declination 2° 35' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE March 7, 1981
CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR
 Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

