

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 34 NR. 3 W
T. 34 NR. 4 W

Cheboygan-Emmet COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 30-31-25-36

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

20" Beech - N59E - 33 links

6" Maple - S42E - 29 links

10" Ironwood - N24W - 51½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found 1" pipe with concrete base in place, as restored by Marcus Schaaf, Registered Land Surveyor, about 1930-1935. Said to have been restored at that time from government evidence, now destroyed in fireline construction.

Corner was placed and witnessed July 27, 1960.

SURVEYORS SEAL

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR

DATE 8/2/60