

SURVEY & REMONUMENTATION COMMISSION
APR 10 1995

STATE OF MICHIGAN
 COUNTY OF LEELANAU
 RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

1994 DEC 30 AM 10:40

Barbara Kirt
 REGISTER OF DEEDS

For corner in Leelanau (County) Located In: Corner Code E-1

1. Public Land Survey	T <u>28N</u> R <u>11W</u>	<u>E-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

#394

LIBER 2 PAGE 91

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Steven P. Bye, in a field survey on December 19, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-1: Northeast corner of Section 5
 Government witness to post set by Orange Risdon, 1850
 Hemlock 24 - N 32 W, 30 links
 Beech 6 - N 17 E, 15 links
 Beech 10 - S 46 E, 47 links
 Beech 18 - S 64 W, 53 links
 Greene in 1906 states 7" maple at corner.
 Brehmer field book 28 state 18" maple at corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1: Northeast corner of Section 5
 Batzer Jr. 1973 survey notes state, corner falls in 20" diameter maple tree
 Witness' of record - set by Batzer Jr. in 1976
 Concrete monument - North 20.00'
 Concrete monument - East 20.00'
 Concrete monument - South 20.00'

APPROVED LAND CORNER
 P.A. 345 OF 1990
 LEELANAU COUNTY

DATE: 5-25-94
 COUNTY REP. W. M. O'Neil

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1: Northeast corner of Section 5
 20" diameter maple tree accepted by the Leelanau County Remonumentation Peer Review Group, May 25, 1994
 Witnesses:
 Concrete monument - North 20.00'
 Concrete monument - East 20.00'
 Concrete monument - South 20.00'
 3" Ash - N 34 W, 22.22'



Signed by Steven P. Bye Date December 20, 1994
 Surveyor's Michigan License No. 35991

#394