

1993

COMMISSION

STATE OF MICHIGAN
COUNTY OF LEELANAU
RECEIVED FOR RECORD

1993 DEC 28 PM 4: 25

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Leelanau

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|-------------|-----|
| 1. Public Land Survey | T 29N R 11W | F-1 |
| | T R | |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

Barbara Kirt
REGISTER OF DEEDS

FILE #331

LIBER 2 PAGE 28

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Steven P. Bye, in a field survey on December 8,, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-1: N 1/4 corner Section 4: G.L.O. "Set 1/4 section post"
Beech 9 N 50 W 25 links
Sugar 14 N 85 E 18 links

R. Max Harris Survey dated May 17, 1984-S 1/4 corner, 1/2" x 3' I.R. set midway on fence near old corner post

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1: N 1/4 corner Section 4: 1/2" x 3' long iron rod found on E-W fenceline fitting Max Harris witnesses

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1: N 1/4 corner Section 4: 1/2" x 3' long iron rod accepted by the Leelanau County Remonumentation Peer Group, November 29, 1993, and re-placed with a 3/4" i.d. galvanized iron pipe 3' long with a brass cap.

22" maple - S 45 W, 4.18'
16" maple - S 88 E, 5.70'
8" maple - N 85 W, 23.78'
16" maple - N 85 W, 23.78'
13" beech - S 10 W, 30.98'

Signed by

Steven P. Bye

Date

12-20-93

Surveyor's Michigan License No.

35991

