

SURVEY &
REMONUMENTATION

1993

REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Tonia (County) Located In: Corner Code ≠

1. Public Land Survey T 5N R 5W M-11
T _____ R _____
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
IONIA COUNTY
RECEIVED FOR RECORD
93 SEP 21 P 3:23
D. J. O'Brien
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Marinus Mulder, in a field survey on June 10, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:
Original corner set by Lucious Lyon, U.S. Deputy Surveyor in 1826. Set wood post witnesses by:
(1) 34" Ash S 24½° W 18 links (2) 11' Beech N 25° W 18 links
PERPETUATION: Captain D.C. Crawford former Ionia County Surveyor has marginal witness notes for this corner on a copy of the G.L.O. notes found in a county surveyors book. He states, 1891 - (1) 1" Maple S 45° W 62 links (2) 2" Maple N 45° W 67½ links. D.C. Crawford again witnessed this corner in 1905 and states: "Clay tile taken out, set iron stake." This corner was recorded by Professional Surveyor, Richard Steadman #11370 Feb. 1, 1972, Liber 1 page 129. Steadman found stones and brick and set ½" pipe and cap next to it.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found ½" pipe and cap by pile of bricks, and stone. Accepted as a faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Removed ½" pipe & cap and replaced with a 3/4" x 24" steel rod and 2 3/4" diameter cap stating "Ionia County P.S. 25863"
Witnesses:
Nail & tag 24" Maple stump Northwest 44.38' (possibly same tree 1891)
Nail & tag power pole Northwest 94.96'
Nail & tag 28" Maple Southwest 40.27' (possibly same tree 1891)
Nail & tag power pole Northeast 84.30'

Signed by Marinus Mulder Date August 31, 1993
Surveyor's Michigan License No. 25863