

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

<u>LAKE</u>	Located In:	Corner Code #	
(County)			
1. Public Land Survey	T <u>20N</u> R <u>13W</u>	<u>J-8</u>	
	T _____ R _____	_____	
	T _____ R _____	_____	
	T _____ R _____	_____	
2. Property Controlling in Section	S <u>23</u> T _____ R _____	<u>12</u>	
	S _____ T _____ R _____	_____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____	
	S _____ T _____ R _____	_____	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, CARL T. KIISKILA, in a field survey on APRIL 29, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

<p><u>J-8</u>                  CERT. OF SURVEY L.2, P.07(SEPT. 9, 1976) &amp; L.3, P.117(9/17/87), C.COLE, PS 817615, "SURVEY MARKER SET".</p>	<p><u>12</u>                  CERT. OF SURVEY L.2, P.07(SEPT.9,1976) &amp; L.3, P.117(9/17/87) BY C.COLE PS817615; "SURVEY MARKER SET".</p>
--	---



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

<p><u>J-8</u>                  ESTABLISHED CTR OF S-23 AT INTERSECTION OF 1/4 LINES (C.COLE IRON FOR CTR OF SECTION IS S85 30'E, 21.37').</p>	<p><u>12</u>                  ESTABLISHED THE SE COR. OF NE1/4 OF NW1/4 OF S-23 PER STANDARD B.L.M. INSTRUCTIONS (C.COLE 1/16 COR IS S83 01'E, 10.76').</p>
---	---

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p><u>J-8</u>                  SET 1"x 41" GALV. PIPE W/PLASTIC PS CAP AND SET BLUE CARSONITE POST W/LDC. TAG.                  7" W.PINE N80 W 39.96' (DROVE NAIL &amp; TAG SOUTH SIDE)                  6" TW.W.PINE N25 E 44.42' (DROVE NAIL &amp; TAG WEST SIDE)                  18" R.OAK S30 E 46.27' (DROVE NAIL &amp; TAG NE SIDE)                  15" R.PINE S25 W 35.93' (DROVE NAIL &amp; TAG EAST SIDE)                  FD 1/2" REROD W/ C.COLE PS CAP &amp; SHORT STEEL                  FM POST FOR GUARD S85 30° E 21.37'.</p>	<p><u>12</u>                  SET 5/8"x 34" REROD W/PLASTIC PS CAP AND BLUE CARSONITE POST W/LOCATION TAG.                  9" W.PINE N15 W 62.36' (DROVE NAIL &amp; TAG WEST SIDE).                  14" W.OAK N70 E 27.24' (DROVE NAIL &amp; TAG SOUTH SIDE).                  2" R.PINE S15 E 8.74' (DROVE NAIL &amp; TAG EAST SIDE).                  9" W.OAK S48 W 28.08' (DROVE NAIL &amp; TAG NW SIDE).                  FD 1/2" REROD W/C.COLE PS CAP &amp; 1 1/2"x 12"                  TALL GALV. PIPE S83 01'E 10.76'.</p>
--	--

Signed by Carl T. Kiiskila Date 5-16-97  
 Surveyor's Michigan License No. 33981